BB CR 106

AD762536

CONTRACT REPORT NO. 106
WSU SDL 72-01

THEORY OF EQUATIONS OF STATE: ELASTIC-PLASTIC EFFECTS II

Prepared by

Washington State University Pullman, Washington

May 1973

Approved for public release; distribution unlimited.

USA BALLISTIC RESEARCH LABORATORIES ABERDEEN PROVING GROUND, MARYLAND

- ·

Destroy this report when it is no longer needed. Do not return it to the originator.

Secondary distribution of this report by originating or sponsoring activity is prohibited.

Additional copies of this report may be obtained from the National Technical Information Service, U.S. Department of Commerce, Springfield, Virginia 22151.

The findings in this report are not to be construed as an official Department of the Army position, unless so designated by other authorized documents.

BRL CONTRACT REPORT NO. 106

FINAL REPORT

THEORY OF EQUATIONS OF STATE: ELASTIC-PLASTIC EFFECTS II

by

G. E. Duvall and D. P. Dandekar

Contract No.

DAADO5-71-C-0136

WSU SDL 72-01 May 1973

Approved for public release; distribution unlimited.

Research Sponsored by the U.S. Army Ballistics Research Laboratory Aberdeen Proving Ground, Maryland


ABSTRACT

After a brief review of the history of material failure studies and of measurements of stored energy in plastically deformed bodies, energy and stress and strain relations are developed for both elastic and plastic deformation in uniaxial strain. The physical effects of plastic deformation are discussed and foundations are laid for thermodynamic calculations of plastically deformed materials. Calculations of both thermodynamic and mechanical parameters are described for uniaxial strain with and without energy storage in internal strains. Conditions of uniaxial strain are found to yield new thermodynamic relations which are useful for synthesizing constitutive relations.

and the state of the second of the state of

TABLE OF CONTENTS

		Page
ABST	RACT	iii
LIST	OF FIGURES	vii
LIST	OF SYMBOLS	ix
I.	INTRODUCTION	1
II.	EXPERIMENTAL MEASUREMENTS OF STORED ENERGY OF DEFORMATION	4
III.	PLASTIC DEFORMATION IN UNIAXIAL STRAIN	16
IV.	THERMODYNAMIC STATES IN PLASTIC FLOW	25
٧.	MECHANICAL CALCULATIONS OF DISLOCATION DENSITY N	49
VI.	DISCUSSION AND CONCLUSIONS	53
APPE	NDICES	
Α.	Addition of Elastic and Plastic Strain Increments	57
В.	Stresses in Elastic-Plastic Deformation	59
С.	Plastic Work and Plastic Strain	61
D.	Stress Cycles for a Linear Elastic-Plastic Material with Constant Yield Stress	65
Ε.	Gibbs Relation	99
F.		101
G.	Evaluation of $(\partial \sigma_{X}/\partial T)$ e e and $(\partial \tau/\partial T)_{Y}$ e $\cdot \cdot \cdot \cdot \cdot \cdot$	103
Н.	T. C. Dislocations	107
Ι.		109
J.	S Sharm Medulus of Al	111
DI	EFERENCES	114
	ISTRIBUTION LIST	119



LIST OF FIGURES

Figure		Page
1.	Time Distribution of Papers on Stored Energy Measurement in Deformed Materials	11
2.	R_D = Work of Deformation/Work of Volume Compression	19
3.	Adiabatic Elastic Compression of an Isotropic Solid in Uniaxial Strain and Hydrostatically	19
4.	Adiabatic Compression and Expansion of an Elastic-Plastic Solid in Uniaxial Strain, OABCD	21
5.	Heat Absorbed in Isothermal Compression	33
6.	Strain and Stress Variations for Isothermal Cycle of Linear Elastic-Plastic Material with Constant Yield Stress	38
7.	Entropy and Plastic Work for the Example of Fig. 6	39
A1.	Arbitrary Displacements in a Continuum	58
Jì.	C_{44} of Al According to the Formula $C_{44} = .2812 \exp[-7.8059/(933.2 - T)] [1-4.79 x 10^{-4}(T-273.2)$] 113.

LIST OF SYMBOLS

```
= work of uniaxial compression
        = internal energy per unit mass
Ε
        = j<sup>th</sup> principal component of stress deviator
e
        = stress deviator
        = entropy per unit mass
        = resolved shear stress
        = j<sup>th</sup> principal component of compressive stress
        = heat transferred in a thermodynamic process
        = volume per unit mass
        = volume dilatation
        = strain
        = Cartesian coordinates
х,у,г
        = ratio of work of deformation to compressive work
Κ
        = bulk modulus
        = Lamé constant
        = Lamé constant
        = stress
        = Poisson's ratio
        = temperature, °K
Τ
        = Helmholtz free energy
Α
        = specific heat at constant volume
        = resolved shear strain
γ
        = energy stored in dislocation
        = dislocation length per unit volume
N
        = dislocation multiplication parameter
        = dislocation multiplication parameter
```

= dislocation multiplication parameter

t = time

distance between imperfections which cause multiplication

a characteristic frequency associated with pinned dislocations

U = activation energy

V_A = shear wave velocity

k = Boltzmann's constant

I. INTRODUCTION

From the earliest times men have been concerned with the conditions of failure of structural materials. Little is known of early Egyptian, Greek and Roman knowledge of the subject, though it is evident from their extensive constructions that they had some effective working rules. During the Renaissance there began to be recorded systematic attempts to study and develop the concepts of material failure. Leonardo da Vinci describes an apparatus for testing the strength of iron wire. In a note on "Testing the Strength of Iron Wires of Various Lengths" he says, "... The object of this test is to find the load an iron wire can carry. Attach an iron wire two braccia long to something that will firmly support it, then attach a basket or any similar container to the wire and feed into the basket some fine sand through a small hole placed at the end of a hopper. A spring is fixed so it will close the hole as soon as the wire breaks. The basket is not upset while falling, since it falls through a very short dis-The weight of sand and the location of the fracture of the wire are to tance. be recorded. The test is repeated several times to check the results. Then a wire of one-half the previous length is tested and the additional weight it carries is recorded; then a wire of one-fourth length is tested and so forth, noting each time the ultimate strength and the location of the fracture." (Timoshenko, 1953) It is particularly interesting to note that even here, in the fifteenth century, the concepts of graduated tests, systematic recording of observations, reproducibility, and variation of a single parameter while holding others constant were fully developed.

Many of the most famous names in science were involved with problems of material failure: Galileo, Euler, Lagrange, Coulomb, Poisson and Kelvin, to name but a few. The basic concepts of plasticity were developed by Barré Saint-Venant and described in several papers during the latter half of the nineteenth century.

This was a period of intensive activity in mechanics and one subject of interest was the search for a suitable criterion for failure of ductile materials. James Clerk Maxwell described the distortion energy concept of failure in a letter to Lord Kelvin in 1856. Although criteria based on this concept are widely accepted today, it did not appear in print until the early part of this century, when it was developed independently by M. T. Huber and R. von Mises.

Since 1934 when E. Orowan, M. Polanyi and G. I. Taylor independently developed the concept, and especially since 1950, failure theories of ductile solids have been based primarily on dislocation behavior. A great body of information on dislocations and their properties and behavior has grown up during the last twenty years, and it is realized that the continuum concepts of failure are, in a microscopic sense, ill founded. It is not possible to displace them, however, because the theory of dislocations is incomplete, because it is much more complicated than continuum theories, because continuum theories work quite well, and because there have been inadequate and only partially effective efforts to bridge the chasm which separates the microscopic behavior of dislocations and the macroscopic behavior of real materials.

Because of this gap between microscopic understanding and macroscopic behavior, there has been an intensive parallel effort to develop and refine continuum concepts of plasticity and yield during recent years.

Until the 1940's there was little concern about the thermodynamics of plastic strain. In 1948 Carl Eckart published an important paper on the thermodynamics of anelastic strain, and Tolman and Fine discussed applications of the Onsager theory of irreversible thermodynamics to problems of plasticity. These were followed by Bridgman's paper of 1950, an article by Reiner in 1958, and then by a spate of articles in the 1960's, of which perhaps the best known are those by B. Coleman and his coworkers, Meixner, and by G. A. Kluitenberg.

Except for Bridgman's paper, most of these have been concerned with general and quite abstract formulations. Indeed it is quite often very difficult to ferret out the underlying physical assumptions on which the work is based.

There appear, then, to be two needs for current work. One is to formulate explicitly and sharply physical foundations for a thermodynamic theory of plasticity which can be grasped by other than trained mathematicians and then to apply these to a relatively simple yet experimentally realistic physical situation. The other is to join the continuum thermodynamic-mechanics developments to dislocation theory in a manner which may be useful to both subjects.

In the present report some progress is made toward each of these goals. Further, since the question of stored energy in plastic work is everpresent and basic to the subject, a brief review of the state of stored energy measurements is given.

The principal results of the theoretical development are that

(1) a point of view is developed that assumes the thermodynamics of plastic deformation to be essentially reversible if the correct variables are chosen;

(2) theoretical calculations and experiments in one-dimensional strain introduce density as a variable, and this leads to phenomena and thermodynamic relations whose utility goes beyond that found for conditions of uniaxial stress;

(3) a combination of thermodynamics and dislocation theory is fruitful for both fields, but the required relations are not completely developed here.

II. EXPERIMENTAL MEASUREMENTS OF STORED ENERGY OF DEFORMATION

Methods for measuring the stored energy in a plastically deformed solid may be put into two categories:

- (1) single-step methods in which all the necessary measurements are made during the deformation;
- (2) two-step methods in which the stored energy is measured following deformation.

2.1 Single-Step Methods

These methods are based on a direct application of the first law of thermodynamics. The stored energy $E_{\rm S}$ is the algebraic sum of the work, W, and the heat, Q. Work may be evaluated from stress and strain measurements. The heat effect is determined either from temperature rise of the specimen deformed under adiabatic conditions or by calorimetry.

The first successful attempt to measure the stored energy in a material undergoing a deformation was made by Hort (1906, 1907). In his experiments, Hort conducted tensile tests in iron in a water calorimeter. The calorimeter was calibrated by electric heating and thermoelastic cooling. For true strains ranging from 0.034 - 0.109, the measurement of stored energy in iron gave values of 2.2 to 5.1 cal/g atom.

Farren and Taylor (1925) determined the heat evolution associated with nearly adiabatic extension of polycrystalline specimens of steel, copper, and aluminum, and of a single crystal of aluminum. The samples were pulled for a short time and work was obtained from a recorded stress-strain curve. The heat evolved was computed from temperature rise in the specimen measured with a thermocouple placed inside an axial hole in the specimen. In 1934, Taylor and Quinney repeated these measurements by deforming steel and copper under torsion to obtain higher strains. Mechanical work was evaluated as in their previous work while

heat was measured both by a thermocouple and by a water calorimeter. The two methods gave similar results.

Maier and Anderson (1934) were the first to measure energy stored during wire drawing by the single step method. Their working metals were aluminum and copper.

The measurement of stored energy under compression was initiated by Kunin and Senilov (1936). They compressed copper by stages in a testing machine; work was measured by special "crusher" gauges. Epifanov and Rebinder (1949) determined the energy stored in chips of aluminum formed by drilling specimens inside a calorimeter. The difference between the energy input to the drill and heat evolved was considered to be the energy stored in the chips.

Eugene (1953, 1954) determined stored energies in lead, copper, and steel by using a freely falling weight to deform the specimens. He obtained stored energy from the difference between the known energy of the weight striking the specimen and the heat effects as measured by its temperature rise. He was able to find very small amounts of stored energy i.e. less than 1% compared to the average of around 10% reported by earlier workers.

Williams (1960) developed a device in which specimens were deformed by freely falling hammers of tungsten carbide. Since the period of contact is less than 2×10^{-3} sec, the deformation induced in the sample is assumed to be adiabatic. The sample is supported by a single thermocouple which measures the temperature rise. The work term is difficult to evaluate because of the mechanical losses due to suspension of the hammers. Heat transfer between the hammers and the sample is small because of the short interval of contact between them. Heat loss due to interaction with the surroundings is minimized by performing the experiments in vacuum. Williams (1961, 1962, 1963) has determined the stored energy in copper and copper-silver alloy by this method.

All of the measurements described above were carried out at room temperature.

Erdmann and Jahoda (1964) designed a device for deforming metal wires at low temperatures and for simultaneously measuring thermal conductivity, electrical conductivity, and heat liberated by the deformation. The experiment is beset with the usual difficulties associated with low temperature experiments which leads to some uncertainty in data reduction.

Williams (1963) also developed yet another apparatus in which the heat developed during the deformation of a sample under tension is measured by the amount of vaporization of a working fluid. The method is generally applicable from room temperature to 77°K. Wolfenden and Appleton (1963) have developed a method similar to the calorimetry of Williams. The fluid used is liquid nitrogen. These authors determined the stored energy in both single and polycrystals of copper and aluminum.

O. W. Dillon (1962, 1966, 1968) in a series of papers determined the heat generated during torsional oscillations of aluminum and copper tubes and the heat generated during the propagation of plastic waves in aluminum. This apparatus is based on the design of Farren and Taylor (1925).

2.2 Two-Step Methods

In these methods a material is deformed plastically by any suitable process. The energy spent in deformation may or may not be measured. The stored energy is determined in a subsequent step by measuring the difference in the thermal behavior of the deformed and a reference specimen in attaining identical final states. The difference in these heat effects is the stored energy of cold work.

Two step methods may be divided into two general classes.

- (1) Annealing methods.
- (2) Reaction methods.
- (1) Annealing methods may be further subdivided into:
- (a) Isothermal annealing, where the stored energy is released at a constant temperature. The energy release may be determined either as a function of time or as a total quantity after a chosen interval of annealing time.
- (b) Anisothermal annealing, where the temperature is increased at a set rate, and the released energy is measured as a function of temperature.

Annealing methods have the added advantage of providing information on the kinetics of the release of stored energy.

(2) Reaction method. In this method the plastically deformed and standard specimens of a material are allowed to react with a molten substance in a calorimeter. The difference between the heats of reaction of standard and deformed specimens is considered to be the stored energy of plastic deformation.

Isothermal Annealing Method

Borelius and his coworkers (1953) seem to have been the first to measure stored energy by this method. They used an isothermal jacket microcalorimeter to investigate the energy evolved at 100°C by aluminum, copper, and zinc immediately after rolling and the energy released at 60°C by aluminum and copper after a lapse of 41 hours and 45 hours respectively. The calorimeter consisted of a vapor thermostat, which provided an isothermal environment for a chamber containing the specimen. The temperature was measured by 30 junctions of sensitive differential thermopile, one set of which was in contact with the chamber. The other set was in contact with the specimen. In operation, the sample was preheated and was rapidly placed in position. The release of heat from the specimen was indicated by the temperature difference across the pile.

Åström (1956, 1964) used the same equipment to study the release of stored energy from aluminum and molybdenum plastically deformed under compression. Gordon (1954, 1955) also used the Borelius et al. type of calorimeter and method to determine energy stored and the kinetics of isothermal release in the range 150°C - 220°C in copper specimens deformed under tension. Bailey and Hirsch (1960) have measured stored energy in silver by this means.

Anisothermal Annealing Methods

There are two basic methods which may be used to obtain results under anisothermal annealing. Both methods are normally used in a differential arrangement where the cold worked sample is compared to an annealed sample. In one case, the "adiabatic method," both samples are heated internally so as to minimize the transfer of heat between samples and the evacuated furnace, and the stored energy is given by the difference between powers required to heat the two samples. In the second method the heat required to raise the temperature of the samples is determined from the transfer of heat from the furnace. The two specimens are placed so as to minimize the thermal interaction between them. This method is called "differential thermal analysis."

The adiabatic method was first used by Quinney and Taylor (1937) to determine stored energies in copper, 70 copper - 30 zinc alloy, aluminum, iron and nickel. Welber (1952) and Clarebrough et al. (1952) built equipment based on the design of Quinney and Taylor. Clarebrough and his coworkers have measured the release of energy stored in nickel and copper deformed by various processes. A summary of these investigations has been given by Boas (1957).

The differential thermal analysis annealing method was first used by Satô (1931). He obtained differential heating curves for cold worked specimens of 70 Cu - 30 Zn, silver, copper, aluminum, iron, nickel and brasses. He annealed standard specimens of identical materials placed side by side, but not

in contact with, a block of silver. The block was heated at the rate of 5°C/min to the temperature at which the standard had been annealed. The heating was repeated without moving the specimens to evaluate the corrections necessary to account for differences between the two specimens not due to cold work.

Henderson and Koehler (1956) have used the technique to study energy release in deformed copper and brass at 77°k. These materials were deformed under compression and the energy release was measured from 77°k to 300°k. Recently Van den Beukel (1963) has repeated Henderson and Koehler's work and has also studied the energy release in deformed nickel, silver, and gold.

Reaction Methods

Reactions which have been used for measuring stored energy of plastic work are dissolution in aqueous solvents and oxidation, and dissolution in liquid tin. In order to measure the energy difference between a deformed and an undeformed sample by measuring the difference between the heats of solution in any substance, it is necessary that the heat of solution be small, the solubility large and the rate of solution at a moderate temperature very rapid. The only solvents which can thus qualify are liquid metals. The application of this method, though started in 1929 by Smith (1929), has been applied with success starting with the works of Bever (1951) and his associates. The method they currently use is given by Howlett et al. (1962). To date, measurements by reaction methods have been limited to copper-gold and silver-gold alloys.

Some other calorimeters which may be used to study release of deformation energy are those constructed by Stansbury et al. (1959), Sherwin (1964), Arndt and Fujita (1963), and Calvet and Prat (1963).

2.3 Status of Stored Energy Measurements and Current Problems

The literature now contains a considerable number of investigations in which the stored energy of plastic deformation has been measured. The distribution of published papers in time between 1900 and 1965 is shown in Figure 1. However, it is still difficult to evaluate critically the relative accuracy of the various methods described above. There are at least three reasons for this situation.

- (1) Scarcity of data for any metal which can be used as a standard. Polycrystalline copper comes closest.
- (2) Reporting only of reproducibility and not accuracy of results by investigators. This is not adequate since accuracy is indicated by reproducibility only in the absence of systematic errors.
- (3) The exact agreement between different methods should be possible only under certain conditions. These conditions concern the characteristics of calorimeters, thermocouple behavior, thermoelastic effects, the process by which deformation is induced in a specimen, etc. However, within limitations imposed by the above three factors, some comparisons are possible; these have been made by Williams (1967) in a recent review article.

An appreciation of the basis for limited comparisons among experimental results may be obtained by simply listing variables which affect the quantity of stored energy in a cold worked material.

A. Material as a variable

- 1. Purity
- 2. Composition of solid solution alloys
- 3. Crystallinity, i.e. single crystal or polycrystal
- 4. If polycrystalline, the effect of grain size and grain structure
- 5. Dislocation characteristics, vacancies, etc.

B. Process of deformation as a variables

- 1. Extension
- 2. Compression




Fig. 1. Time Distribution of Papers on Stored Energy Measurement in Deformed Materials

- 3. Torsion
- 4. Rolling
- 5. Wire drawing
- 6. Cutting processes such as filing, drilling, etc.
- 7. Deformation in fatigue, i.e. cyclic loading
- 8. Degree and rate of deformation
- C. Effects of temperature on cold work.

Present activity in the field is directed toward evolving a model or models which will explain the mechanisms of energy storage and release. The present interpretation of energy storage is based on ideas of the production of inhomogeneous lattice strains and the generation of imperfections like dislocations, point defects, stacking faults in hexagonal materials, twins and reduction of order in alloys. However, a quantitative interpretation of stored energy processes remains uncertain primarily due to lack of a precise accepted definition of cold work and to the degree of inaccuracy in measurement of stored energy.

It will be seen from the above description that the stored energy of cold work has been measured exclusively in metals. Even among metals, copper, nickel, aluminum, silver and iron, have been most commonly investigated; infrequent or solitary measurements of stored energy of cold work in zinc, lead tin do exist. The stored energy of cold work has also been investigated in a few alloys, notably in Cu-Ag, Cu-Au, and Cu-Ni. The absence of any such investigation in ionic compounds is striking considering the large amount of work done in LiF, MgO and other ionic solids (see for example, (Gilman, 1969)).

Laboratories where investigations on the stored energy of cold work and its release mechanism are being carried out at present are few. The prominent laboratories and persons involved in these measurements are:

(1) Oak Ridge National Laboratory, Oak Ridge, Tenn. R. O. Williams, A. Wolfenden, and R. A. Vandermeer.

- (2) Dept. of Metallurgy, MIT, Cambridge, Mass. M. B. Bever and A. L. Titchener
- (3) Dept. of Metallurgical Engineering, IIT, Illinois, P. Gordon
- (4) Cavendish Laboratory, Cambridge, U.K., J. E. Bailey and P. B. Hirsch
- (5) Dept. of Metallurgy, Univ. of Liverpool, U.K., A. S. Appleton
- (6) Div. of Tribophysics, C.S.I.R.O., Univ. of Melbourne, Australia,
 L. M. Clarebrough, M. E. Hargreaves, M. H. Loretto and A. K. Head

Present ideas about the mechanisms of storage of cold work energy and its release are given in what follows.

The small percentage (5 to 10%) of the energy expended in plastically deforming a metal, which is stored in the deformed metal, is associated with defects generated during the deformation. A significant part of the stored energy is associated with the distribution and density of dislocations in the bulk of the deformed metal. The remaining part of the stored energy is associated with imperfections like point defects, vacancies, twins, stacking faults, etc. However, this partition of stored energy among the various imperfections as well as the absolute value of the stored energy is dependent on purity, degree of deformation, temperature of deformation, and grain size. In general, the energy stored during plastic deformation of a metal increases with the degree of deformation, and may or may not reach a saturation before fracturing. Also for a given extent of deformation, the value of stored energy increases with decreasing temperature of deformation of a metal. In general, the higher the purity of a metal, the lower the stored energy of cold work. And lastly, for metals, stored energy for a given deformation increases with decrease in grain size for small strains (≤ 0.20) and then becomes relatively independent of grain size for large strains.

The inference about apportionment of stored energy among the various imperfections in a metal is made from the correlation of release of stored

energy with changes in other physical properties, e.g., changes in electrical resistivity, density and with structural studies using conventional metallographic techniques and electron transmission microscopy.

The release of stored energy proceeds in two or more stages. However the various processes by which the annealed state is reached are classified into two categories -- recovery and recrystallization. The apportionment of the released energy into these two classes is based on the definition that recovery encompasses all those annealing phenomena which precede recrystallization in any local region of the material. On the other hand, recrystallization is defined as the appearance of comparatively strain-free grains which are separated from the deformed matrix or from other recrystallized grains by high-angle grain boundaries and alternatively, recrystallization may be defined as the appearance of virtually strain-free grains which have grown in the deformed matrix by the movement of large angle grain boundaries.

A common feature in all the investigations on metals and alloys is that recrystallization is accompanied by a marked release of stored energy as well as a decrease in electrical resistivity and an increase in density. Electron microscope observations indicate that this release of energy and concomittant changes in the electrical resistivity and density are associated with a change in the distribution and density of dislocations. Hence the magnitude of energy released during recrystallization can be associated with the energy of the dislocations. Bailey and Hirsch (1960) seem to have been the first to establish such an association, which they did for polycrystalline silver. However, Clarebrough et al. (1961) disputed the conclusion of Bailey and Hirsch that theory of flow stress involving piled up groups of dislocations is not applicable to silver.

For recovery the experimental situation is not so well defined. The ratio of stored energy released during recovery to total stored energy varies between 0.03 to 0.7 depending on the purity of material, strain, and temperature

of deformation. Evaluations of changes in other properties accompanying recovery in metals deformed at room temperature have been aided insignificantly by structural observations. For metals deformed at the temperature of liquid nitrogen the energy stored is four times that for deformation at room temperature. The annealing of point defects is assumed to contribute to the large releases of energy associated with recovery below room temperature, in addition to the contribution of other imperfections. Bailey and Hirsch (1960) could not detect any change in the dislocation density and distribution before and after recovery in silver, although during the recovery half the total stored energy was liberated.

In alloys a major source of energy release during recovery may be associated with the return of short range order destroyed by deformation.

To sum up, existing experimental measurements on the stored energy of cold work and the release of the energy with concomittant variation in the physical structural properties in the most extensively studied metal, i.e. copper, is not sufficient to test validity of the two existing theories of work hardening of pure metals. In one theory, due to Friedel (1955) and Seeger et al. (1957), the flow stress is determined by long-range stresses due to groups of piled up dislocations. In the second theory, due to Cottrell (1953), Basinski (1959), and Hirsch (1958), the flow stress is determined by short-range interactions between crossing dislocations.

III. PLASTIC DEFORMATION IN UNIAXIAL STRAIN

Definitions and Basic Relations

The uniaxial strain condition applies to plane wave compression and rarefaction. If wave propagation is in the x-direction, the work of uniaxial compression is

$$dW = -Vp_X d\epsilon_X = -p_X dV$$
 (1)

where $p_x = -\sigma_x = compressive$ stress in the x-direction and $d\epsilon_x \equiv dV/V$. Principal axes of stress and strain lie in and normal to the direction of propagation. If E is internal energy of unit mass,

$$dE = dQ - Vp_{x} d\epsilon_{x}$$
 (2)

where dQ is heat communicated to the mass element by conduction or other means. The work term of Eq. (1) can be expressed as work of compression plus work of deformation by introducing stress and strain deviators, S_i and e_i :

$$dW = -Vp \ d\theta + V \sum_{j} S_{j} \ de_{j}$$
 (3)

where

$$S_{j} = -p_{j} + p \quad) \tag{4a}$$

$$S_{j} = -p_{j} + p \qquad (4a)$$

$$e_{j} = \epsilon_{j} - \theta/3 \qquad (4b)$$

$$S_{X} = 4\tau/3, S_{Y} = S_{Z} = -2\tau/3$$
 (5a)

$$\tau = -(p_X - p_Y)/2 \tag{5b}$$

$$e_x = 2\epsilon_x/3$$
, $e_y = e_z = -\epsilon_x/3$, $d\theta = d\epsilon_x$. (5c)

Using these relations, Eq. (3) becomes

$$dW = -Vpd_{\varepsilon_X} + V[(4\tau/3) \cdot (2/3)d_{\varepsilon_X} - 2(2\tau/3) (-d_{\varepsilon_X}/3)]$$

$$= -Vpd_{\varepsilon_{x}} + 4V_{\tau}d_{\varepsilon_{x}}/3 \tag{6}$$

$$= -Vpd_{\varepsilon_{\mathbf{X}}} (1 - 4\tau/3p) \tag{7}$$

$$= -Vpd\varepsilon_{x} (1 - R_{D})$$
 (8)

where R_{D} is the ratio of work of deformation to compressive work. For elastic changes the constitutive relations can be written in incremental form to account for changes in the elastic moduli with strain:

$$dp = -Kd\theta = -Kd\epsilon_{x}$$
 (9)

$$dS_{j} = 2\mu de_{j} \tag{10}$$

or
$$d\sigma_{X} = (\lambda + 2\mu)d\epsilon_{X}$$
 (11)

$$d\sigma_{y} = \lambda d\varepsilon_{x} = d\sigma_{z}$$
 (12)

$$d_{\tau} = \mu d_{\varepsilon_{\mathbf{X}}} \tag{13}$$

where K is bulk modulus and λ , μ are the Lamé constants. Values of K, λ , μ depend on whether strain occurs at constant temperature or constant entropy. Isothermal moduli will be denoted K^T , λ^T , μ^T ; isentropic moduli K^S , λ^S , μ^S . When the superscript is omitted the meaning is obvious or the question is indifferent.

We can invoke the condition of uniaxial strain to obtain:

$$dp_{y} = -d\sigma_{y} = vdp_{x}/(1-v) = dp_{z}$$
 (14)

$$dp = (dp_x/3) (1+v)/(1-v)$$
 (15)

$$d\tau = -(dp_{\nu}/2) (1-2\nu)/(1-\nu)$$
 (16)

where $v = (\lambda/2)/(\lambda+\mu)$ = Poisson's ratio, which may depend on strain and temperature or entropy.

For small strains, Eqs. (11) - (13) can be integrated assuming moduli to be constant:

$$\sigma_{\mathbf{x}} = (\lambda + 2\mu) \, \epsilon_{\mathbf{x}} \tag{17}$$

$$\sigma_{y} = \lambda \varepsilon_{x} = \sigma_{z}$$
 (18)

$$\tau = \mu \varepsilon_{\mathbf{x}} \tag{19}$$

$$\varepsilon_{x} = (V - V_{0})/V_{0} \tag{20}$$

where V is specific volume and ${\rm V}_{\rm O}$ denotes a reference, stress and strain-free state. For this case

$$R_{D} = 2(1 - 2v)/(1 + v) \tag{21}$$


(see Eq. (8)). The dependence of $R_{\rm D}$ on ν is shown in Fig. 2.

This discussion of elastic strain provides a framework within which questions of plasticity may be discussed and it is important to note that the work of plastic deformation is bounded by the work of volume compression and that of elastic deformation. This is illustrated in Fig. 3 where curves of hydrostatic and uniaxial compression under adiabatic conditions are compared. For elastic strain, adiabatic conditions are also isentropic, so the slopes of OM and ON are $-(V_0/V)K^S$ and $(-V_0/V)(\lambda^S+2\mu^S)$, respectively. Since $P_X=P-4\tau/3$, the work of deformation is

$$W_{d} = -\int p_{\chi} dV + \int p dV = (4/3) \int_{\tau} dV \qquad (22)$$

which is just V_0 times the area of the sliver between ON and OM of Fig. 3. As noted in Fig. 2, this may be small or large depending on the value of v.

When the strain cycle is completed by allowing the material to expand back to p or $p_X = 0$, the elastically strained sample under adiabatic conditions simply returns to the point 0 along the curve of compression, OA or OB. The






Figure 3 Adiabatic elastic compression of an isotropic solid in uniaxial strain and hydrostatically.

plastically deforming material, on the other hand, completes part of a hysteresis loop as shown in Fig. 4. The sections of this loop are formed according to the following process. Starting at point 0 the sample is compressed uniaxially until it starts to deform plastically at A. Along AB the plastic deformation is continuous until the maximum value of p_x is reached. At B the applied stress is allowed to start decreasing, $\sigma_x - \sigma_y$ is reduced and expansion occurs elastically. At C, $\sigma_y - \sigma_x$ has once more reached the yield value and plastic deformation continues from C to D. There are now two questions to be considered:

- (i) What is the amount of plastic work done along the sections AB and CD? (Q1)
- (ii) Can a thermodynamic state be defined at each point? (Q2) We consider these questions in the order stated.




Figure 4 Adiabatic compression and expansion of an elastic-plastic solid in uniaxial strain, OABCD.

3.2 Computation of the Plastic Work

An important convention in the theory of plasticity is the assumption that when plastic and elastic strain are occurring simultaneously, each increment in total strain can be decomposed into a sum of plastic and elastic increments, i.e.

$$d\varepsilon = d\varepsilon^{e} + d\varepsilon^{p} \tag{23}$$

where superscripts "e" and "p" stand for "elastic" and "plastic."

This convention is discussed in Appendix A. It is also common to assume that there is no plastic contribution to the density change, so that

$$d\varepsilon_{\mathbf{j}} = d\varepsilon_{\mathbf{j}}^{\mathbf{e}} + d\varepsilon_{\mathbf{j}}^{\mathbf{p}} = d\varepsilon_{\mathbf{j}} + d\theta/3$$

$$d\theta = d\theta^{\mathbf{e}}; \quad d\theta^{\mathbf{p}} = 0$$

$$d\varepsilon_{\mathbf{j}} = d\varepsilon_{\mathbf{j}}^{\mathbf{e}} + d\varepsilon_{\mathbf{j}}^{\mathbf{p}}$$

$$(24a)$$

Then increments in the work of plastic and elastic deformation are given, respectively, by

$$dW_{dp} = V \sum_{j} S_{j} de_{j}^{p} \qquad plastic \qquad (25)$$

$$dW$$
de = $V \sum_{j} S_{j} de_{j}^{e}$ elastic (26)

Since $dW_{\mbox{\scriptsize dp}}$ is the only plastic work in this process, i.e. volume compression is purely elastic, we write henceforth

$$dW_p \equiv dW_{dp}$$
.

We also assume that stresses are supported only by the elastic strains,

$$dS_{j} = 2\mu de_{j}^{e}. \tag{27}$$

A physical basis for Eq. (27) is discussed in Appendix B.

The condition of uniaxial strain requires only that total strain ϵ_y and ϵ_z vanish, i.e.

$$d\varepsilon_y^p + d\varepsilon_y^e = 0 (28a)$$

$$d\varepsilon_z^p + d\varepsilon_z^e = 0. (28b)$$

Because of symmetry about the x-axis

$$d\varepsilon_{y}^{e} = d\varepsilon_{z}^{e}. \tag{29}$$

From Eqs. (5a), (10) and (27)

$$dS_{x} = 4d\tau/3 = 2\mu de_{x}^{e}$$
 (30)

$$dS_{y} = -2d\tau/3 = 2\mu \ de_{y}^{e}$$
 (31)

$$dS_x - dS_y = 2d\tau = 2\mu d(e_x^e - e_y^e)$$

$$d_{\tau} = 2\mu d_{\gamma}^{e} \tag{32}$$

where

٤

$$d_{\gamma}^{e} \equiv d(e_{\chi}^{e} - e_{y}^{e})/2 = (d\epsilon_{\chi}^{e} - d\epsilon_{y}^{e})/2. \tag{33}$$

From Eq. (6) the total incremental work of deformation is

$$dW_d = 4V\tau \ d\varepsilon_x/3. \tag{34}$$

From Eqs. (26) and (30) - (32) the incremental work of elastic deformation is

$$dW_{de} = 8V\tau d\gamma^{e}/3$$
$$= (4V\tau/3\mu)d\tau . \tag{35}$$

The incremental work of plastic deformation is obtained by subtracting Eq. (35) from (34):

$$dW_{D} = (4/3) V_{\tau} (d\varepsilon_{x} - d\tau/\mu)$$
 (36)

where τ = $\pm Y/2$ depending on whether the process is compressive or expansive. Y > 0 is the yield stress as given by the von Mises condition.

Eq. (36) can be obtained directly from Eqs. (4b), (24a) and (25). It can also be written in the form of Eq. (C5) in Appendix C:

$$dW_{p} = 2V\tau d\varepsilon_{x}^{p}$$
 (37)

If $y^p \equiv (e_x^p - e_y^p)/2$, Eq. (37) can also be written as

$$dW_{p} = (8/3)V_{\tau} d_{\gamma}^{p}$$
(38)

The increment in elastic work represented by Eq. (35) can easily be seen to be reversible:

$$dW_{de} = (2V/3\mu) d(\tau^2).$$
 (39)

As $|\tau|$ goes up and down, so does W_{de} .

The plastic work is irreversible by definition,

$$dW_{p} \geq 0. (40)$$

This is readily illustrated with reference to Fig. 4. During elastic compression along OA in Fig. 4, $d\epsilon_{\chi}^{\ p}=0$, $\tau<0$, $d\tau<0$, $d\psi_{p}=0$. Along AB, $\tau\leq0$ and $d\epsilon_{\chi}<0$. For a material which doesn't work-harden, $d\tau=0$, so $d\psi_{p}>0$. If work-hardening occurs, $d\tau<0$, but $d\tau/\mu$ cannot exceed $d\epsilon_{\chi}$ in magnitude since $d\epsilon_{\chi}=d\tau/\mu$ when compression is elastic. So in that case, too, $d\psi_{p}>0$. Along BC the material is expanding elastically, τ is changing from negative to positive sign, $d\epsilon_{\chi}^{\ p}=0$ and $d\psi_{p}=0$. Along CD, $\tau>0$, $d\epsilon_{\chi}>0$ and again $d\psi_{p}>0$ from Eq. (36) by the same argument applied to the path AB. Also $d\epsilon_{\chi}^{\ p}>0$ along CD.

Eq. (36) or (37) provides an answer to question 1, raised above. We now turn attention to Q2.

IV. THERMODYNAMIC STATES IN PLASTIC FLOW

The simplest observations of plastic yield tell us a great deal about the process. Bend a piece of iron wire back and forth between your fingers a few times. It gets hot and is still solid iron. The first result is obvious; the second is verified by chemical and metallurgical analysis. It is, in fact, very hard to detect any changes in the material, but we know that some have occurred since repeated bending breaks the wire, yet it does not break at the first bending. Property changes due to bending are more obvious in a piece of copper. Bending produces marked increases in bending resistance before it breaks.

In developing a thermodynamic theory to deal with such conditions we can assume either that plastic work changes the material or that it does not. It is clear from our simple experiment that the latter assumption is a fairly good one and we accept it for the moment and consider its consequences.

4.1 Plastic Work Converted Entirely to Heat

Even though this be true, there is a difficulty associated with plastic strain which is illustrated in Fig. 4. On reversal of stress at any point, say B, the stress-strain curve is not retraced, even though the process be isothermal. Yet if we persist in the reversal we can find a sequence of applied forces which will return the material to its initial state under this condition that plastic work produces no material changes. This is illustrated in Figs. 6 and 7, to be discussed farther on in this section. This is a kind of geometric irreversibility to be distinguished from irreversibility of material properties. It complicates description of thermodynamic processes but does not essentially change the postulate that plastic working has put the material in a thermodynamic state characterized by the added heat, ΔQ . The situation is somewhat like that of a fluid. If we deform a viscous fluid at constant density, we recognize that heating occurs, but we suppose the final state to be describable in terms of thermodynamic

parameters of the original fluid. The fact that particular molecules have different neighbors is considered inconsequential.

In the same way it is inconsequential that neighbors may have changed after plastic deformation; thermodynamic parameters are the same. It is, in a sense, unimportant that the macroscopic form of the material has changed and that this makes a difference in the external behavior. This difference is observable in the solid and not in the fluid because the solid atoms undergo elastic strain during deformation, whereas the fluid atoms do not.

With such considerations as foundation, we are led to a <u>Fundamental</u> Assumption:

There is always an elastically strained state imbedded in every deformed state. This elastic state is inherently reversible and can be recovered by suitable processes.

This assumption implies that an internal energy, E, exists and that it is a function of the elastic strains, ε^{e} , entropy, S, and perhaps of internal or microscopic strain variables. A representation of the internal energy function can be obtained by noting that each increment of work on the system is the sum of an elastic and a plastic increment. By the Fundamental Assumption the elastic increment is recoverable, so increments in internal energy can be written as

$$dE = TdS + dW_{Q}$$
 (41)

where dW_e depends on the elastic strain increments. According to the first law this increase in internal energy must equal the total work done on the system plus the heat absorbed from the surroundings:

$$TdS + dW_e = dW + dQ. (42)$$

This leads directly to the <u>Gibbs relation</u> for the increase in entropy produced in the process:

$$dS = (dW_p + dQ) / T$$
 (43)

where $dW_p = dW - dW_e$.

According to Eq. (41) and the foregoing assumptions, internal energy can be expressed in terms of entropy and the elastic strains. For example

$$E = E(S, \varepsilon_X^e, \varepsilon_V^e)$$

Changes in entropy result solely from the agitations and elastic displacement of atoms; there is no entropy directly associated with the plastic strain. Nonetheless an apparent dependence of state on plastic strains may exist because of the procedure required to separate dW into elastic and plastic parts. For example, from Eqs. (1) and (37) we find that

$$dW_e = dW - dW_p = V_{\sigma_X} d_{\varepsilon_X} - 2V_{\tau} d_{\varepsilon_X}^p$$

so that

$$E = E(S, \varepsilon_x, \varepsilon_x^p).$$

The appearance of $\epsilon_X^{\ p}$ in this potential is illusory. It does not imply a physical dependence of E on plastic strain. Failure to realize this fact has led to some confusion in other work.

It will be useful to tabulate various forms of the internal energy, but first we note that increments in the Helmholtz potential will be in the form

$$dA = -SdT + dW_{\triangle}$$
 (44)

and that the entropy and temperature are given by

$$S = -(\partial A/\partial T)_{e} e$$
 (45)

$$T = (\partial E/\partial S)_{\epsilon} e$$
 (46)

where subscript ϵ^{e} indicates that all elastic strains are to be held constant. Using the equations developed earlier, we have the following representations: From Eqs. (6) and (35),

$$dW_{e} = -Vpd_{\varepsilon_{X}} + 8V_{\tau}d_{\Upsilon}^{e}/3$$
 (47)

$$E = E(S, \varepsilon_{X}, \gamma^{e})$$
 (48)

$$A = A(T, \epsilon_x, \gamma^e). \tag{49}$$

Since $Vd_{\epsilon_X}=dV$, this is equivalent to a representation in which V and γ^e are the mechanical variables.

From Eqs. (1) and (37),

$$dW_e = dW - dW_p = V\sigma_X d\varepsilon_X - 2V\tau d\varepsilon_X^p$$
 (50)

$$E = E(S, \varepsilon_{x}, \varepsilon_{x}^{p})$$
 (51)

$$A = A(T, \varepsilon_x, \varepsilon_x^p). \tag{52}$$

From Eqs. (1) and (38)

$$dW_e = dW - dW_p = V_{\sigma_X} d\varepsilon_X - 8V_{\tau} d\gamma^p/3$$
 (53)

$$E = E(S, \varepsilon_{x}, \gamma^{p})$$
 (54)

$$A = A(T, \varepsilon_{v}, \gamma^{p}). \tag{55}$$

A representation which shows the dependence of state functions on elastic strains and temperature exclusively is

$$dW_{e} = V(\sigma_{x} d\varepsilon_{x}^{e} + 2\sigma_{y} d\varepsilon_{y}^{e})$$
 (56)

so that

$$E = E(S, \varepsilon_x^e, \varepsilon_y^e)$$
 (57)

$$A = A(T, \varepsilon_X^e, \varepsilon_y^e)$$
 (58)

Since entropy is defined as

$$S = -\partial A/\partial T$$

it depends on the same variables as A.

The functions E, A, S, etc. are state functions, so their differentials are exact and lead to various Maxwell-like relations and compatibility conditions which are later shown to be useful.

Some common thermodynamic observables take unusual forms when these representations are used. Specific heat is an example.

From Eq. (49),

$$c_{V} = T(\partial S/\partial T)_{\varepsilon_{X}} = T(\partial S/\partial T)_{\varepsilon_{X}, \gamma} e^{+T(\partial S/\partial \gamma^{e})}_{T, \varepsilon_{X}} (\partial \gamma^{e}/\partial T)_{\varepsilon_{X}}$$
(59a)

From Eq. (52),

$$c_{V} = T(\partial S/\partial T)_{\varepsilon_{X}} = T(\partial S/\partial T)_{\varepsilon_{X}, \varepsilon_{X}} p + T(\partial S/\partial \varepsilon_{X}^{p})_{\varepsilon_{X}, T} (\partial \varepsilon_{X}^{p}/\partial T)_{x}$$
(59b)

From Eq. (55),

$$c_{V} = T(\partial S/\partial T)_{\varepsilon_{X}} = T(\partial S/\partial T)_{\varepsilon_{X}, \gamma}^{p} + T(\partial S/\partial \gamma^{p})_{\varepsilon_{X}, T}^{p} (\partial \gamma^{p}/\partial T)_{\varepsilon_{X}}^{e}$$
 (59c)

For Eq. (56) C_V is not defined but can be obtained by invoking the condition

$$d\varepsilon = d\varepsilon_{x}^{e} + 2d\varepsilon_{v}^{e}, \qquad (60)$$

which follows directly from Eq. (24a) and the symmetry of uniaxial strain. In this way one of the three forms of Eq. (59) will be obtained.

One may reasonably ask whether derivatives like $(\partial S/\partial \epsilon_X^p)_{T,\epsilon_X}$, which appears in Eq. (59b), are physically meaningful in view of the nature of plastic strain. Since plastic strain enters in a contrived way, as explained in the paragraph following Eq. (43), they can always be expressed in terms of more obviously thermodynamic derivatives. For example, calculate dS from Eqs. (52) and (58):

$$dS = (\partial S/\partial T) p dT + (\partial S/\partial \varepsilon_{x})_{T,\varepsilon_{x}} p d\varepsilon_{x}$$

$$+ (\partial S/\partial \varepsilon_{x}^{p})_{T,\varepsilon_{x}} d\varepsilon_{x}^{p}$$

$$dS = (\partial S/\partial T) e_{x} e_{,\varepsilon_{y}} e^{-dT} + (\partial S/\partial \varepsilon_{x}^{e})_{T,\varepsilon_{y}} e^{-d\varepsilon_{x}^{e}}$$

$$+ (\partial S/\partial T)_{T,\varepsilon_{x}} e^{-d\varepsilon_{y}^{e}}.$$

Since we wish to obtain $\partial S/\partial \epsilon_{\chi}^{\ p}$ in terms of elastic strain derivatives, write $d\epsilon_{\chi}^{\ e}$ and $d\epsilon_{y}^{\ e}$ in terms of $d\epsilon_{\chi}$ and $d\epsilon_{\chi}^{\ p}$; i.e.

$$d\varepsilon_{x}^{e} = d\varepsilon_{x} - d\varepsilon_{x}^{p}$$

$$d\varepsilon_{y}^{e} = -d\varepsilon_{y}^{p} = d\varepsilon_{x}^{p}/2.$$

· Then equating the two values of dS gives

$$0 = [(\partial S/\partial T)_{\varepsilon_{X}\varepsilon_{X}}^{p} - (\partial S/\partial T)_{\varepsilon_{X}}^{e} e_{\varepsilon_{y}}^{e}]dT + [(\partial S/\partial \varepsilon_{X})_{T,\varepsilon_{X}}^{p}]$$

$$-(\partial S/\partial \varepsilon_{X}^{e})_{T,\varepsilon_{y}}^{e} e^{]d\varepsilon_{X}} + [(\partial S/\partial \varepsilon_{X}^{p})_{T,\varepsilon_{X}}^{e}]$$

$$-(1/2)(\partial S/\partial \varepsilon_{y}^{e})_{T,\varepsilon_{X}}^{e} e^{+} (\partial S/\partial \varepsilon_{X}^{e})_{T,\varepsilon_{y}}^{e} e^{]d\varepsilon_{X}}^{e}. (61)$$

Specification of the deformation process requires specification of dT and two strain variables, so coefficients of dT, $d\varepsilon_X^e$, $d\varepsilon_X^p$ in Eq. (61) must vanish independently; therefore

$$(\partial S/\partial \varepsilon_{x}^{p})_{T,\varepsilon_{x}} = (1/2) (\partial S/\varepsilon_{y}^{e})_{T,\varepsilon_{x}} e^{-(\partial S/\partial \varepsilon_{x}^{e})_{T,\varepsilon_{y}}}$$
 (62)

From Eqs. (44) and (56)

$$dA = -SdT + V_{\sigma_{X}} d\epsilon_{X}^{e} + 2V_{\sigma_{y}} d\epsilon_{y}^{e}$$

$$S = -\partial A/\partial T; \quad V_{\sigma_{X}} = \partial A/\partial \epsilon_{X}^{e}$$

$$\partial S/\partial \epsilon_{X}^{e} = -\partial^{2}A/\partial T\partial \epsilon_{X}^{e} = -(\partial V_{\sigma_{X}}/\partial T)_{\epsilon_{X}} e\epsilon_{y}^{e}$$

$$\partial S/\partial \epsilon_{y}^{e} = -2(\partial V_{\sigma_{y}}/\partial T)_{\epsilon_{y}} e\epsilon_{x}^{e}$$

Then

$$(\partial S/\partial \varepsilon_{x}^{p})_{T,\varepsilon_{x}} = V(\partial \sigma_{x}/\partial T)_{\varepsilon_{x}} e_{\varepsilon_{y}} e^{-V(\partial \sigma_{y}/\partial T)}_{\varepsilon_{x}} e_{\varepsilon_{y}} e$$

$$= 2V(\partial \tau/\partial T) e e e$$

$$\varepsilon_{X} \varepsilon_{y}$$
(63)

The derivative on the r.h.s. of Eq. (63) is taken with ϵ_x^e , ϵ_y^e constant. Since this insures that no strain is occurring,

$$(\partial \tau / \partial T)_{\substack{\epsilon \\ \chi}} e_{\substack{\epsilon \\ y}} e = (\partial \tau / \partial T)_{\substack{\epsilon \\ \chi}, \substack{\epsilon \\ \chi}} e = (\partial \tau / \partial T)_{\substack{\epsilon \\ \chi}, \substack{\gamma \\ \epsilon \\ \chi}} e \text{ etc.}$$

In order to evaluate changes in entropy under the assumptions of this section, dQ of Eq. (43) must be specified. For an adiabatic process, dQ = 0, but the sample gets hotter as the process continues, so a repeating cycle doesn't exist.

To calculate dQ for an isothermal process consider incremental compression from a reference state under three different conditions, Fig. 5. Compression along AD is adiabatic and is accompanied by plastic work ΔW_p ; no heat is absorbed. Compression along AC is isentropic; the amount of heat removed just compensates for the plastic work. Compression along AB is isothermal and it is along this path that we wish to calculate ΔQ . For the situation shown $\Delta Q < 0$, i.e. heat must be removed to compensate for the plastic work. By the first law the change in internal energy in going from A to B is equal to the total work done plus the heat absorbed,

$$E_{R} - E_{\Lambda} = dW + dQ \tag{64}$$

where

$$\Delta W = V_{\sigma_X} d_{\varepsilon_X}$$

According to Appendix F, dQ can be expressed in terms of incremental changes in specific volume, elastic strain and plastic work:

$$dQ = T(\partial p/\partial T)_{V,\gamma} e dV - (8VT/3)(\partial \tau/\partial T)_{V,\gamma} e d\gamma^{e} - dW_{p}$$
 (65)




Figure 5 Heat absorbed in isothermal compression

The net entropy production in the sample is obtained by combining Eqs. (43) and (65):

$$dS = (1/T)(dW_{p} + dQ)$$

$$= (3p/3T)_{V,Y} e^{dV} - (8V/3)(3\tau/3T)_{V,Y} e^{dY} e^{Q}$$
(66)

This is a remarkable result and one which has been noted by Bridgman for uniaxial stress: Entropy absorbed by the sample under isothermal conditions is given by the elastic changes alone, even in the presence of plastic work.

Equation (66) may be obtained more directly with minimal reference to the physical processes by using the fact that entropy is a state function, so changes in entropy can be obtained by direct differentiation. Thus from Eq. (49) with $Vd\epsilon_{\nu}$ replaced by dV,

$$S = S(T, V, \gamma^e)$$

$$dS = (\partial S/\partial T)_{V,\gamma} e^{dT + (\partial S/\partial V)_{T,\gamma}} e^{dV + (\partial S/\partial \gamma^e)_{T,V}} d\gamma^e$$
(67)

Since S is derived from the Helmholtz potential A and

$$dA = -SdT - pdV + (8V\tau/3) d\gamma^{e},$$

the last two coefficients in Eq. (67) can be obtained by equating crossderivatives of A:

$$\partial S/\partial V = -\partial^2 A/\partial T\partial V = \partial p/\partial T \tag{68}$$

$$\partial S/\partial \gamma^{e} = -\partial^{2}A/\partial T\partial \gamma^{e} = -(8V/3)(\partial \tau/\partial T)$$
 (69)

Setting dT = 0 and substituting Eqs. (68) and (69) into (67) yields Eq. (66). While this procedure is economical in mathematical operations, it does not reveal the physical content of the result so clearly as the earlier procedure.

Since dS is an exact differential, the cross derivatives of its coefficients must be equal. Thus

$$(\partial C_{V\gamma}/\partial V)_{T,\gamma} e = (T \partial^2 p/\partial T^2)_{V,\gamma} e$$
 (70a)

$$(\partial C_{V\gamma}/\partial \gamma^{e})_{V,T} = -(8V/3)(\partial^{2}\tau/\partial T^{2})_{V,\gamma} e$$
 (70b)

$$\partial^2 p / \partial T \partial \gamma^e = -(8/3) \partial (V \partial \tau / \partial T) / \partial V$$
 (70c)

The bulk modulus, K, may depend on γ^e , thus leading to a dependence of p on γ^e , but this is likely to be small. Setting it equal to zero implies that

$$\partial (V\partial \tau/\partial T)/\partial V = 0$$

or

$$V(\partial \tau/\partial T)_{V,\gamma} e = f(\gamma^{e},T)$$
 (71)

In Eqs. (70) $C_{V\gamma}$ has been written for (1/T)(3S/3T) $_{V,\gamma}e$. Here again the dependence of $C_{V\gamma}$ on $_{\gamma}e$ is likely to be small so

$$(\partial^2 \tau / \partial T^2)_{V,\gamma}^e \simeq 0. \tag{72}$$

Most materials will be found to yield before the linear relation between τ and γ^e is violated. Setting γ = 2μ γ^e with μ independent of γ^e , Eq. (71) becomes

$$(\partial \mu/\partial T)_{V,\gamma}e^{}=g(T)/V$$
 (73)

while Eq. (72) suggests that

$$(\partial^2 \mu / \partial T^2)_{V,\gamma} e \simeq 0. \tag{74}$$

Equations (73) and (74) together imply that

$$\partial \mu / \partial T = b/V$$
 (75a)

or

$$\mu = \mu_0 + b(T/V - T_0/V_0) + \phi(V)$$
 (75b)

where $\phi(V_0)=0$. If experiments reveal that $\partial \mu/\partial T$ depends on temperature (which it certainly does near the melting temperature) then the assumption that C_{V_∞} is independent of γ^e is invalid.

For computational purposes it is convenient to write

$$(\partial p/\partial T)_{V,\gamma} e = r C_{V\gamma}/V$$
 (76)

where Γ is the Gruneisen parameter. This coefficient is slowly varying and normally, but not necessarily, positive. Taking $\tau = 2\mu\gamma^e$ as before, the second coefficient in Eq. (66) becomes

$$-(16V \gamma^{e}/3) (\partial \mu/\partial T)_{V,\gamma^{e}}$$
 (77)

Since $\partial \mu/\partial T$ is normally negative, this coefficient has the sign of γ^e , which is frequently, but not always, negative in compression and positive in tension. Taking ΓC_V and $V \partial \mu/\partial T$ to be constants, we have for the entropy change

$$\oint dS = \Gamma C_V \oint d\varepsilon_x + (8V/3) |\partial \mu/\partial T| \oint d(\gamma^e)^2 = 0$$
 (78)

This illustrates in a particular case the general result which follows from the assumption that E and A are state functions.

Equation (78) refers to entropy change in the sample during an isothermal cycle. The entropy of the reservoir in which the sample is imbedded will be found to increase in a cycle in the amount

$$\Delta S = \oint (dW^p/T).$$

A simple example of the calculation outlined in this section is detailed in Appendix D and in Figs. 6 and 7. In this example it is assumed that the material is linearly elastic up to the yield point (point A in Fig. 4) and that the yield stress, Y > O, is constant throughout the isothermal process. Under these conditions the cycle OABFO of Fig. 4 can be followed explicitly but simply. The turning point F is determined by equating the tensile stress developed along the curve of elastic expansion, OF, to the stress along DF. With F determined in this way, stress, elastic strain, plastic strain and entropy of the sample return to their starting values at O, whereas the plastic work of deformation and the entropy of the heat reservoir do not. These results are shown in Figs. 6 and 7. With non-linear elastic behavior the computation is more difficult but results are essentially the same.

A similar calculation can be made for the isentropic case, curve AC of Fig. 5. Then elastic constants are isentropic instead of isothermal and T must be calculated in order to determine entropy delivered to the reservoir. In this case entropy of the reservoir increases monotonically. Temperature is a state function of S, V, γ^e according to Eqs. (46) and (48), as

$$dT = (\partial T/\partial S)_{V,\gamma} e^{dS + (\partial T/\partial V)_{S,\gamma} e^{dV + (\partial T/\partial \gamma^e)_{S,V}} d\gamma^e.$$

Set dS = 0 for isentropic compression and use the equalities among crossderivatives of E to obtain

$$dT = -(\partial p/\partial S)_{V,\gamma} e^{-dV + (8V/3)(\partial \tau/\partial S)_{V,\gamma} e^{-d\gamma}}.$$
 (79)

It will now be found that T goes through a maximum and a minimum during each cycle and returns to its initial value at the end of a cycle, since dT is an




Figure 6 Strain and stress variations for isothermal cycle of linear elastic-plastic material with constant yield stress. (See Appendix D.) Abscissa is $\int \left|d\sigma_{\chi}\right|$.




Figure 7 Entropy and plastic work for the example of Figure 6.

exact differential. Since the dependence of observables on entropy is not measured directly, this case appears to be of lesser interest than the isothermal case.

Heat conduction effects are not normally significant in stress wave propagation, so compression is inclined to be adiabatic. V, γ^e , S, T do not repeat cyclically as stress is cycled because plastic work is retained in the sample as heat. One can ask for the fate of mechanical and thermal variables as p_X increases to its maximum value and returns to zero. It may be of further interest to inquire what processes are required to return it from this final state to its initial state, but this is not normally of interest, for example, in a shock wave problem.

In the adiabatic case, both entropy and temperature are changed with each increment of plastic work. The sample is isolated from the universe so the only source of entropy is the plastic work done on the specimen. Then

$$dS = dW_{D}/T. (80)$$

Combining this with Eqs. (67) to (69) yields

$$dT = (T/C_{V\gamma}) [dW_p/T - (\partial p/\partial T)_{V,\gamma} e dV$$

$$+ (8V/3) (\partial \tau/\partial T)_{V,\gamma} e d\gamma^e]$$
(81)

4.2 Plastic Work Partially Converted to Internal Strains.
Thermodynamic Potentials

The admission that plastic work changes material properties has rather profound effects on thermodynamic concepts though the magnitude of energy involved is not very large; probably not more than 5 to 10% of the plastic work is stored in this way, and the total may be much less. The most directly

observed effect of internal energy storage is work-hardening; in some materials the yield stress may be doubled by plastic work. Although this effect results from partition of the plastic work, it is in itself not a thermodynamic effect and so must be taken as an empirical result.

In order to treat this case thermodynamically, we still consider that at each point on a deformation path the material is in a reproducible thermodynamic state, but that the state depends on an internal variable as well as the external variables of the previous section. The physical and mechanical characteristics of plastically deformed material are commonly ascribed to the creation and entanglement of dislocations, so dislocation parameters are used as internal thermodynamic variables. Dillon and Kratchovil (1970) have used dislocation density and dislocation entanglement as two internal variables. However the present state of understanding of dislocations hardly seems to justify the use of two variables. Here the dislocation density will be taken as the sole internal variable. Let this be denoted by N, the total dislocation length per unit volume of material. Denote the energy stored per unit length of dislocation by $\rho r \approx b^2 \mu/2$ (Nabarro, p. 694). Then changes in internal energy are reversible in the variables S, V, $\gamma^{\rm e}$, N:

$$dE = TdS - pdV + (8V_{\tau}/3) d_{\gamma}^{e} + rdN,$$
 (82)

implying that

$$E = E(S, V, \gamma^e, N)$$
 (83)

$$A = A(T, V, \gamma^{e}, N). \tag{84}$$

These potentials being given, the change in entropy resulting from isothermal compression can be calculated as before (dT = 0):

$$dS = (\partial S/\partial V)_{T,\gamma^e,N} dV + (\partial S/\partial \gamma^e)_{T,V,N} d\gamma^e$$

$$+ (\partial S/\partial N)_{T,V,\gamma^e} d\gamma^e.$$

Using the compatibility relations derived from A this can be written

$$dS = (\partial p/\partial T)_{V,\gamma} e_{,N} dV - (8V/3)(\partial \tau/\partial T)_{V,\gamma} e_{,N} d\gamma^{e}$$

+
$$(\partial r/\partial T)$$
 dN (85)

4.3 Compatibility Relations

dS is an exact differential since it is derived from the state function, Eq. (84). This implies that the coefficients in Eq. (85) satisfy the following conditions:

$$(\partial^2 p/\partial T \partial \gamma^e)_{V,N} = -(8/3)\{\partial [V(\partial \tau/\partial T)_{V,\gamma^e,N}] / \partial V\}_{\gamma^e,N}$$
 (86a)

$$(\partial^2 p/\partial N\partial T)_{V,\gamma} e = -(\partial^2 r/\partial V\partial T)_{\gamma} e_{,N}$$
(86b)

$$(\partial^{2}r/\partial T\partial \gamma^{e})_{V,N} = (8/3) \{\partial[V(\partial \tau/\partial T)_{V,\gamma^{e},N}] / \partial N\}_{V,\gamma^{e}}$$
(86c)

Assume that yield always occurs at sufficiently small shear that shear stress and strain are linearly related,

$$\tau = 2\mu \gamma^{e} \tag{87}$$

$$\partial \mu / \partial \gamma^e \equiv 0.$$
 (88)

Assume also that pressure is independent of elastic shear strain. While this is not necessarily true, it is highly plausible:

$$\partial p/\partial \gamma^e \equiv 0.$$
 (89)

From Nabarro (p. 694) one finds that

$$r \simeq b^2 V_{\mu}/2. \tag{90}$$

The implications of Eqs. (86) to (90) are derived in Appendix I. They are

$$(\partial p/\partial T)_{\gamma}^{e}, V, N = f_{2}(T, V)$$
 (91)

$$(\partial(\mu V)/\partial T)_{\gamma} e_{\gamma V,N} = f_{\gamma}(T)$$
 (92)

or

$$p = f(T,V) + g(V,N)$$
 (93)

$$\mu V = F(T) + G(V,N) \tag{94}$$

Equations (91) to (94) are useful in constructing equations of state for the classes of materials described here. For example, Eq. (93) limits the Helmholtz potential to the form

$$A(T,V,\gamma^{e},N) = - \{f(T,V)dV - \{g(V,N)dV + \phi(T,N,\gamma^{e})\}$$
 (95)

where, f, g and ϕ are arbitrary functions of the variables indicated.

The possibility of deriving relations like those of Eqs. (91) to (95) is a consequence of the assumption of uniaxial strain, on which this entire calculation is based. Under conditions of uniaxial strain it is possible for density changes and plastic strain to occur simultaneously. In uniaxial stress this is not the case: thermodynamic potentials do not depend on both V and γ , so compatibility relations of the kind derived above do not exist. It does not seem likely that going to a more general process than uniaxial strain would produce additional information, except in anisotropic materials.

4.4 Gibbs Relation Including Stored Energy

The Gibbs relation for entropy production in an arbitrary process can be derived as before. Equate the increase in internal energy of unit mass to the sum of work done and heat added; this gives the analogue of Eq. (42):

$$TdS + dW_e + rdN = dW + dQ$$
 (96)

and the Gibbs relation becomes

$$TdS = dW - dW_e - rdN + dQ$$
$$= dW_p - rdN + dQ .$$
(97)

Equation (97) is a formalization of the basic assumption that energy stored in dislocations can be recovered. Plastic work may be required to move dislocations, but this is directly associated with plastic strain and appears as heat. Since the energy of dislocations derives from local strain fields, internal strain could equally well be used as a parameter. N is more convenient since extensive work exists on the properties of dislocations and their behavior. When N is sufficiently large, dislocations interact and their energy is no longer proportional to N. Such interactions can be partially accounted for by letting r be a function of N. But we shall ignore them here and introduce self-annihilation and annealing of dislocations to prevent N from growing indefinitely.

If the compression process is carried out at a finite rate, Eq. (97) gives the rate of entropy production:

$$TdS/dt = dW_{D}/dt - rdN/dt + dQ/dt$$
 (98)

In the event that either dW_p/dt or dN/dt is rate-dependent, this will lead to entropy production beyond that given by Eq. (85).

4.5 Equilibrium Values of N; An Anomaly

In order to complete the thermodynamic description, a procedure is required for calculating N. Two routes are available for obtaining the required information. One is to continue the formal thermodynamic description of the process and so to determine the bounds on equilibrium values set by the

compatibility relations. Such information can be augmented by statistical calculations for determination of entropy and lattice calculations for determining such parameters as r. The latter has already been noted in the preceding paragraph. The second is to apply some of the formalism of dislocation theory and expressions for multiplication rates to relate, for example, dislocation density to strain history. Both of these routes are considered here. We start with the thermodynamic development.

The great question about the thermodynamics of dislocations is whether equilibrium ever exists in the sense that the appropriate potential is minimized with respect to the various parameters. Here we assume that an equilibrium density N exists and we find how it is related to other material parameters. For this purpose we consider Eq. (82) and its companion for dA:

$$dE = TdS - pdV + (8V /3) d_Y^e + rdN$$
 (82)

$$dA = -SdT - pdV + (8V /3) d_{\gamma}^{e} + rdN.$$
 (99)

Because Eqs. (82) and (99) are exact differentials, the cross derivatives of their coefficients must be equal. Those involving N are

$$(\partial T/\partial N) = (\partial r/\partial S) V, Y^{e}, N$$
(100a)

$$(\partial p/\partial N) = -(\partial r/\partial V)$$

$$S, V, \gamma^{e} = -(\partial r/\partial V)$$

$$S, \gamma^{e}, N$$
(100b)

$$(16V_{\gamma}^{e}/3) (\partial \mu/\partial N) = (\partial r/\partial \gamma^{e})_{S,V,N}$$
(100c)

$$(\partial S/\partial N)_{T,V,\gamma}^{e} = -(\partial r/\partial T)_{V,\gamma}^{e},N$$

$$= (b^{2}V/2) (\partial \mu/\partial T)_{V,\gamma}^{e},N$$
(100d)

$$-(\partial p/\partial N)_{T,V,\gamma}e = (\partial r/\partial V)_{T,\gamma}e_{,N}$$
 (100e)

$$(16V_{\gamma}^{e}/3) (\partial_{\mu}/\partial N)_{T,V,\gamma}^{e} = (\partial_{\tau}/\partial_{\gamma}^{e})_{T,V,N}$$
 (100f)

Here the approximations of Eqs. (87), (88) and (90) have been used.

To see the utility of Eqs. (100), consider Eq. (100a). The right hand side can be written

$$(3r/3S) = (b^{2}V/2) (3\mu/3S) V_{,\gamma}^{e}, N$$

$$= (b^{2}V/2) (3\mu/3T) V_{,\gamma}^{e}, N V_{,\gamma}^{e}, N$$

$$= (b^{2}VT/2C_{V\gamma}^{e}) (3\mu/3T) V_{,\gamma}^{e}, N$$
(101a)

where

$$C_{V\gamma N} \equiv T(\partial S/\partial T)_{V,\gamma} e_{,N}$$
 (101b)

By regarding N as a function of (T, V, γ^e, p) , we have

$$(\partial N/\partial T)_{S,V,\gamma}e^{=(\partial N/\partial T)_{V,\gamma}e_{,p}} + (\partial N/\partial p)_{T,V,\gamma}e^{(\partial p/\partial T)_{S,V,\gamma}e}$$

It seems quite plausible that $\,p\,$ is insensitive to $\,N\,$; then the second term is negligible and

$$(\partial N/\partial T)_{S,V,\gamma}^{e} \simeq (\partial N/\partial T)_{V,\gamma}^{e}_{p}$$
 (101c)

Equations (100a), (101a) and (101c) combine to give

$$(\partial N/\partial T)_{V,\gamma^e,p} = 2C_{V\gamma N}/[b^2VT(\partial \mu/\partial T)_{V,\gamma^e,N}]$$
 (102)

This is a curious and unexpected result. $\partial \mu/\partial T$ is known to be negative and $C_{V\gamma N}$ is positive, therefore $\partial N/\partial T < 0$. But one expects the equilibrium number of dislocations to increase with T for the following reasons. Energy is required to form dislocations, so that an assembly which includes dislocations contains eigenstates of higher energy than a perfect lattice. Under equilibrium conditions these higher energy states are unoccupied at low temperatures but at sufficiently high temperatures they may be occupied. Just where the argument leading to Eq. (102) fails is not clear, but it is clear that the reason for the failure must be determined before other relations obtained from the compatibility condition can be safely used.

Changes in $C_{V\gamma N}$ with N, γ^e and V can be obtained from the expression for dS when dT \neq 0. Equation (85) is then replaced by

$$dS = (C_{V \times N}/T)dT + (\partial p/\partial T)dV - (8V/3) (\partial \tau/\partial T) d\gamma^{e} - (\partial r/\partial T)dN.$$
 (103)

Then

$$\partial(C_{V_{\gamma}N}/T)/\partial N = -\partial^2 r/\partial T^2$$
 (104a)

$$\partial(C_{V_YN}/T)/\partial \gamma^e = -(8V/3) \partial^2 \tau/\partial T^2$$
 (104b)

$$a(C_{V \setminus N}/T)/aV = a^2 p/aT^2$$
 (104c)

If Eqs. (87) and (90) are assumed true, Eqs. (104a) and (104b) combine to yield the result

$$\partial C_{V_{\gamma}N}/\partial N - (3b^2/18) \partial C_{V_{\gamma}N}/\partial (\gamma^e)^2 = 0$$
. (105)

This has solutions of the form

$$c_{V_YN} = f[(N + 6\gamma^{e^2}/b^2), V,T],$$
 (106)

which shows an interesting relation in the dependence of $C_{V\gamma N}$ on N and γ^e . It does not appear to be susceptible to test with present information.

The physical consequences of relations like those of Eqs. (100) and (104) have been illustrated but not exhausted. For the present, however, we forsake further development of these relations.

V. MECHANICAL CALCULATIONS OF DISLOCATION DENSITY, N

5.1 Formalism

As a consequence of plastic work, dislocation densities may be generated which are much greater than equilibrium values calculated in the previous section. These may represent substantial quantities of stored energy, and at sufficiently high temperatures this should be released as heat with a consequent reduction of N. The thermodynamic effects of non-equilibrium changes of N are derived from the Gibbs relation in the form of Eq. (100). This indicates that dN/dt is the quantity of prime interest.

A form frequently used for dN/dt is quoted by Webster (1966):

$$dN/dt = aN - bN^2 + S_0.$$
 (107)

The first term represents creation of dislocations by regenerative processes, the second represents self-annihilation, and the third represents spontaneous nucleation of dislocations under the influence of externally applied forces. Equation (107) can be integrated directly to yield

$$N = [A - B\theta \exp(-\kappa t)] / [1 + \theta \exp(-\kappa t)]$$
 (108)

where
$$\kappa = (a^2 + 4b S_0)^{1/2}$$

$$A = (a/2b) (1 + \kappa/a)$$

$$B = -(a/2b) (1 - \kappa/a)$$

$$\theta = (A - N_i)/(B + N_i)$$

$$N_i = \text{dislocation density at } t = 0$$

For
$$S_0 = 0$$
,
 $N = a N_i \exp(at) / [a + N_i b (exp (at) - 1)].$ (109)

The Gilman relation for multiple cross glide has

$$aN = mbv N = N_{\uparrow} f \dot{\gamma}^p$$

where $\dot{\gamma}^p$ is plastic strain rate. Then, for small multiplication, changes in N are proportional to plastic strain. This relation has been widely used in discussion of dynamic failure (Asay, et al. 1972).

For large t and $S_0 = 0$, Eq. (109) goes to

$$N \equiv N_S = a/b \tag{110}$$

This is the saturation value of N; it is unrelated to the thermal equilibrium value discussed in the previous section. From Eq. (109), $1/a \equiv t_e$ is a characteristic time for equilibration. Then Eq. (110) can be rewritten in the form

$$1/N - 1/N_S = (1/N_i - 1/N_S) \exp(-t/t_e);$$
 (111)

 $\mathbf{t}_{\mathbf{e}}$ is assumed to be the order of a few multiplication times and is discussed in Appendix H:

$$t_e = \alpha s/v_A - (\alpha/n)/ \ln [1 - \exp(-U/kT)]$$
 (112)

where s = distance between imperfections which cause multiplication

n = a characteristic frequency associated with pinned dislocations

 $U = U_0 (1 - \sigma/\sigma_0)$ is an activation energy

v = shear wave velocity

 α = a number the order of ten

 σ = effective stress driving the dislocation

 σ_0 = critical or threshold stress

Equation (112) is to be applied if $\sigma < \sigma_0$. For $\sigma \ge \sigma_0$,

$$t_{e} = \alpha s/v_{s}. \tag{113}$$

If U/kT \sim 10, Eq. (112) gives $t_e \sim 10^{-4}$ seconds, which is very long on the scale of shock experiments. On the other hand, Eq. (113) is the order of 10^{-12} for \sim 100 pinning points per million lattice sites, a time which is completely negligible.

5.2 Applications to Shock Processes

If we assume the Gilman relation for multiplication and ignore self-annihilation, we have

$$dN/dt = mbvN = m_Y^{\bullet p}$$

or

$$dN = md_Y^*p$$
.

Each increment in plastic work is also proportional to d_{Υ}^{p} :

$$dW_{p} = (8V\tau/3)d\gamma^{p}.$$

The increment in stored energy is rdN and its ratio to $dW_{\rm p}$ is

$$rdN/dW_p = 3mr/8V_{\tau} = 3b^2 \mu m/16\tau.$$

For m = 10^{11} , b = 3 x 10^{-8} , μ = 2.7 x 10^{11} and τ = 5 x 10^9 dynes/cm², this ratio is

$$rdN/dW_{p} \simeq .9 \times 10^{-3} = .09\%$$

This value is to be compared with the oft-quoted value of "5 to 10%." This can be achieved by making τ very much smaller, as in a static test, or by increasing m. A value of 0.5 kilobars in a static test on soft aluminum is not out of reason, in which case the ratio of stored energy to plastic work goes to 0.9%. Moreover m is not precisely known and may be increased several-fold without seriously violating any experiments. In fact some of the dynamic failure data

for aluminum suggest that m may be as large as 2.5 x 10^{12} in shock experiments. Then taking $\tau = 5$ kb again,

$$rdN/dW_p \approx 2.3\%$$

which is approaching the usually quoted range for stored energy. The possibility that plastic stored energy in shock compression is less than static values must be admitted.

For comparison, a similar calculation for the case of uniaxial stress leads to the ratio

$$rdN/dW_p = mr/VY = mb^2 \mu/2Y$$

where $Y=2\tau$ is the yield stress in simple tension. This does not differ significantly from the value for uniaxial strain.

The total plastic work generated when aluminum is shocked to 100kb is approximately $W_p = .15 \text{ kb}$ cc/g or 1.5 x 10^8 ergs/g. Equating 5% of this to rN where $r \approx 4.5 \times 10^{-5}$ gives

$$N = .05 \times 1.5 \times 10^8 / 4.5 \times 10^{-5} = 1.6 \times 10^{11}$$
.

This is small for a saturation value of N and it suggests that in the small times available under shock conditions, saturation of dislocation density may not occur.


VI. DISCUSSION AND CONCLUSIONS

A simple and approximate model for treating the thermodynamics of elastic-plastic solids has been initiated here but not completed. Its application to conditions of unixial strain shows that the additional thermodynamic degree of freedom compared to uniaxial stress gives some potentially interesting new compatibility relations which can be checked against various experimental data. It is also suggested that shock experiments which have uniaxial strain geometry may be useful in evaluating dislocation concepts and those of elastic-plastic thermodynamics.

The point of view espoused here is a novel one. It is common to speak of an elastic-plastic system as being "essentially irreversible" or "immersed in a sea of irreversibility." The view expressed here, but not completely developed, is that the elastic-plastic state is completely reversible in the variables which are natural to the state and that the apparent irreversibility associated with inability to retrace a α - ϵ state is an awkward consequence of geometry and is not essentially related to the question of reversibility of the process. Having stated such a hypothesis, one must then make some decision about the role of stored plastic work. For many purposes the problem is indifferent to this decision because the quantity of stored energy is small. But when the stored energy is related to dislocation density, the thermodynamic formalism suggests that this may provide some new avenues for investigation of the role of dislocations in plastic deformation.

					•					
					į		, , ,			
					•					
			,				•			
									4	
	•									
		•					* •	٠	. 4	
					•	:	I			
		•						•		
						4				
			•		2					
						v +				
					•		i			
	•				•					
				à		•				
.•										
		e e			•					
		,								
					•				_	
									9	
	•				•					
							•			
									•	

APPENDICES



APPENDIX A

Addition of Elastic and Plastic Strain Increments

In Fig. Al are shown two points of a continuum, 0 and P, separated by a small distance \vec{s} . Application of an external stress forces 0 to A and P to B. When the stress is removed, A relaxes to Q and B to T. We have from the figure

$$\vec{OA} = \vec{u}, \vec{PB} = \vec{u} + d\vec{u}$$

 $d\vec{u} = \vec{s} \cdot \nabla \vec{u}$ (A1)

$$\overrightarrow{AQ} = \overrightarrow{u}', \overrightarrow{BT} = \overrightarrow{u}' + d\overrightarrow{u}'$$

 $d\overrightarrow{u}' = (\overrightarrow{s} + d\overrightarrow{u}) \cdot \nabla \overrightarrow{u}'$ (A2)

$$\overrightarrow{00} = \overrightarrow{u}'', \overrightarrow{PT} = \overrightarrow{u}'' + d\overrightarrow{u}''$$

$$d\overrightarrow{u}'' = \overrightarrow{s} \cdot \nabla \overrightarrow{u}'' \qquad (A3)$$

In writing Eqs. (A1) - (A3) the vector change $d\vec{u}$, etc has been expanded in a Taylor series in \vec{s} or \vec{s} + $d\vec{u}$ and all but the lowest order term discarded.

 $d\vec{u}''$ is identified as the plastic displacement, $-d\vec{u}'$ the elastic displacement and $d\vec{u}$ as the total displacement. Then

$$-d\vec{u}' + d\vec{u}'' = \vec{s} \cdot (-\nabla \vec{u}' + \nabla \vec{u}'') - d\vec{u} \cdot \nabla \vec{u}'$$

$$= \vec{s} \cdot (-\nabla \vec{u}' + \nabla \vec{u}'' - \nabla \vec{u} \cdot \nabla \vec{u}')$$
(A4)

The vector gradient, $\nabla \vec{u}$, can be decomposed into a strain tensor $\underline{\varepsilon}$ and a rotation tensor $\underline{\theta}$:

$$\nabla \vec{u} = \underline{\varepsilon} + \underline{\theta}$$
where $\underline{\varepsilon} = (1/2) (\nabla \vec{u} + \widetilde{\nabla u})$

$$\underline{\theta} = (1/2) (\nabla \vec{u} - \widetilde{\nabla u})$$

and $\overrightarrow{\nabla u}$ is the transpose of $\nabla \overrightarrow{u}$.

Then Eq. (A4) becomes

$$-d\vec{u}' + d\vec{u}'' = \vec{s} \cdot (-\underline{\varepsilon}' + \underline{\varepsilon}'' - \underline{\varepsilon}' \cdot \underline{\varepsilon}'' - \underline{\theta}' \cdot \underline{\theta}'' + \text{rotation terms}).$$

Then if $\underline{\varepsilon}'$, $\underline{\varepsilon}''$, $\underline{\theta}''$, $\underline{\theta}'''$ are infinitesimal, the 2nd order terms can be neglected so

that

$$d\vec{u} = -d\vec{u}' + d\vec{u}'' = \vec{s} \cdot (-\underline{\varepsilon}' + \underline{\varepsilon}'' + \text{rotation terms}) = \vec{s} \cdot (\underline{\varepsilon} + \underline{\theta})$$

so that

$$\underline{\underline{\varepsilon}} = -\underline{\underline{\varepsilon}}' + \underline{\underline{\varepsilon}}'' = \underline{\underline{\varepsilon}}^{\mathbf{e}} + \underline{\underline{\varepsilon}}^{\mathbf{p}}$$
 (A5)

where $\underline{\varepsilon}^e$ has been set equal to $-\underline{\varepsilon}^i$. In a finite deformation process the relation can be applied to each increment in strain so that

$$d_{\underline{\varepsilon}} = d_{\underline{\varepsilon}}^{e} + d_{\underline{\varepsilon}}^{p} \tag{A6}$$




Figure Al Arbitrary displacements in a continuum

APPENDIX B

Stresses in Elastic-Plastic Deformation

The conventional assumption in elastic-plastic theory is that stress is supported by the elastic strain and there exists no contribution from the plastic strain. This appears plausible if one examines the microscopic behavior of a plastically deforming material from the point of view of dislocation theory.

Plastic deformation is synonymous with motion and generation of dislocations. In most materials dislocations probably move at all stress levels, so there is no such thing as a yield point and there is no truly elastic behavior. But in practice the yield point concept is useful and the yield point itself may be taken to be the point at which large numbers of dislocations are set in motion. The motion of dislocations is inhibited by the existence of energy barriers which must be overcome by combination of stored elastic energy and thermal fluctuations of atoms. So, for example, one may consider a strained, work hardening solid as one in which many dislocations exist but are momentarily immobilized or "pinned" by energy barriers. If applied stress is held constant, dislocations may occasionally overcome a barrier and move to the next barrier, thus contributing to the plastic deformation by creep.

If the external stress is increased, local strain energy is increased around the pinning points, more dislocations are moved through pinning points and pass on until they are pinned again. If it is assumed that dislocations move freely between pinning points, the plastic strain which results from their motion requires no part of the applied stress; i.e. the applied stress is supported entirely by the elastic part of the strain. It does follow, however, that a relaxation process may exist. For example, an increment in stress increases local strain energy around pinning points and increases probability

that dislocations will break free of their pinning points and move on until pinned again. However, the probability of a dislocation breaking free is time dependent because it depends on thermal fluctuations as well as strain energy. This means that an increment in stress will produce an immediate elastic strain, and that, as time passes, dislocations escape their pins, move, and are repinned, so that a plastic strain develops. Or the original increment in strain is reduced as the pinned dislocations escape from their barriers and the elastic strain is reduced. This concept can be expressed quantitatively in the following way

$$d\sigma = \rho a^{2} d\varepsilon^{e}$$

$$= \rho a^{2} (d\varepsilon - d\varepsilon^{p})$$

$$= \rho a^{2} d\varepsilon - a^{2} (d\varepsilon^{p}/dt) dt$$

$$d\sigma/dt = \rho a^{2} d\varepsilon/dt - \rho a^{2} d\varepsilon^{p}/dt.$$
(B1)

In terms of stress and strain deviators this translates to

$$dS_{j}/dt = 2\mu de_{j}/dt - 2\mu de_{j}^{p}/dt$$
$$= 2\mu de_{j}/dt - F(S,e)$$
(B2)

where F is a relaxation function.

Equations (B1) and (B2) are both based on the assumption that dislocations move between pinning points without drag. If this is not true, then a viscous contribution to the stress appears:

$$d\sigma = \rho a^2 d\epsilon^p + \eta d\epsilon_p$$

or
$$dS_{j}/dt = 2\mu \ de_{j}/dt - 2\mu \ de_{j}^{p}/dt + 2\eta \ de_{j}^{p}/dt$$
 (B3)

where $\dot{e}_{i}^{p} \equiv de_{i}^{p}/dt$.

or

Plastic Work and Plastic Strain

$$d\varepsilon_{x}^{p} = d\varepsilon_{x} - d\varepsilon_{x}^{e}$$
 (C1)

Eq. (24a)
$$d\theta = d\varepsilon_x + 2d\varepsilon_y = d\varepsilon_x^e + 2d\varepsilon_y^e + (d\varepsilon_x^p + 2d\varepsilon_y^p)$$

$$= d\varepsilon_x^e + 2d\varepsilon_y^e + 0$$

$$= d\varepsilon_x \quad \text{by Eq. (28a).}$$

$$d\varepsilon_v^e = d\varepsilon_x/2 - d\varepsilon_x^e/2 = d\varepsilon_x^p/2$$

$$d\sigma_{x} \approx \lambda d\theta + 2\mu d\varepsilon_{x}^{e}$$
 by Eq. (27)

$$d\sigma_y = \lambda d\theta + 2\mu d\epsilon_y^e$$
 by Eq. (27)

$$d(\sigma_{x} - \sigma_{y}) = 2\mu(d\epsilon_{x}^{e} - d\epsilon_{y}^{e}) = 2\mu(d\epsilon_{x}^{e} - d\epsilon_{x}^{p}/2)$$
 (C2)

$$d\tau = [d(\sigma_x - \sigma_y)]/2 = \mu d\epsilon_x^e - \mu d\epsilon_x^p/2$$

$$d\varepsilon_{x}^{e} = d\tau/\mu + d\varepsilon_{x}^{p}/2 \tag{C3}$$

so
$$d\epsilon_{\chi}^{p} = d\epsilon_{\chi} - d\tau/\mu - d\epsilon_{\chi}^{p}/2$$
 from Eqs. (C1) and (C3)

$$d\varepsilon_{x}^{p} = (2/3) (d\varepsilon_{x} - d\tau/\mu)$$
 (C4)

Combine this with Eq. (36) to obtain

$$dW_{p} = \frac{4}{3} V_{\tau} \cdot \frac{3}{2} d\varepsilon_{x}^{p} = \frac{2V_{\tau} d\varepsilon_{x}^{p}}{\frac{1}{2}}$$
 (C5)

From Eq. (25)
$$dW_p = V(S_x de_x^p + 2S_y de_y^p)$$

= $\frac{4}{3} V_T (de_x^p - de_y^p)$ from Eq. (30) and (31) (C6)

$$de_{x} = d\epsilon_{x} - d\theta/3 = d\epsilon_{x}^{e} + d\epsilon_{x}^{p} - d\theta/3$$

$$de_{y} = d\epsilon_{y} - d\theta/3 = d\epsilon_{y}^{e} + d\epsilon_{y}^{p} - d\theta/3$$

$$de_{x} - de_{y} = d\epsilon_{x} - d\epsilon_{y}$$

$$(de_{x}^{e} - de_{y}^{e}) + (de_{x}^{p} - de_{y}^{p}) = (d\epsilon_{x}^{e} - d\epsilon_{y}^{e}) + (d\epsilon_{x}^{p} - d\epsilon_{y}^{p}) \qquad (C7)$$

$$de_{x}^{e} - de_{y}^{e} = d\tau/\mu \text{ by Eq. (S2)}$$

$$d\epsilon_{x}^{e} - d\epsilon_{y}^{e} = d\tau/\mu \text{ by Eq. (C2)}$$

Therefore Eq. (C7) becomes

$$de_{x}^{p} - de_{y}^{p} = d\epsilon_{x}^{p} - d\epsilon_{y}^{p}$$

$$= \frac{3}{2} d\epsilon_{x}^{p}$$
since $d\epsilon_{x}^{p} + 2d\epsilon_{y}^{p} = 0$.

Substituting this into Eq. (C6) yields

$$dW_p = \frac{4}{3} V_{\tau} \cdot \frac{3}{2} d\epsilon_{\chi}^p = 2V_{\tau} d\epsilon_{\chi}^p$$

in agreement with Eq. (C5).

Note that the following argument is faulty:

$$de_{x} = d\epsilon_{x} - d\theta/3 = \frac{2}{3} d\epsilon_{x}$$

$$de_{y} = d\epsilon_{y} - d\theta/3 = \frac{1}{3} d\epsilon_{x}$$

$$de_{x} - de_{y} = d\epsilon_{x}$$

$$(de_{x}^{e} - de_{y}^{e}) + (de_{x}^{p} - de_{y}^{p}) = d\epsilon_{x}^{p} + d\epsilon_{x}^{e}$$

$$de_{x}^{p} - de_{y}^{p} = d\epsilon_{x}^{p}$$
and
$$de_{x}^{e} - de_{y}^{e} = d\epsilon_{x}^{e}$$

This result contradicts Eq. (C8) and is not true because the non-zero values of $d\epsilon_y^{\ e}$ and $d\epsilon_y^{\ p}$ have been ignored in obtaining the final relation.

APPENDIX D

Stress Cycles for a Linear Elastic-Plastic Material with Constant Yield Stress.

All Plastic Work is Converted to Heat.

$$T = 300^{\circ} K$$

$$\lambda$$
 = constant = 582 kb

$$\mu$$
 = constant = 274 kb

$$Y = constant = 10 kb$$

$$e_{v} = e_{z}$$

$$-V(\partial \sigma_{x}/\partial T)_{\varepsilon_{y}\varepsilon_{y}}p = 16.8 \times 10^{-3} \text{ kbcc/g}^{\circ}$$

$$V_0 = .37 \text{ cm}^3/\text{g}$$

$$C_V = 8.4 \times 10^{-3} \text{ kbcc/g}^{\circ}$$

$$\sigma_y = \sigma_z$$

$$\varepsilon_y = \varepsilon_z = 0$$

$$\varepsilon_{\mathbf{v}}^{\mathbf{p}} = \varepsilon_{\mathbf{z}}^{\mathbf{p}}$$

Initial Conditions at 0 (Figs. 3 and 4)

$$\sigma_{x} = \sigma_{y} = 0;$$
 $\varepsilon_{x} = \varepsilon_{x}^{e} = \varepsilon_{x}^{p} = \varepsilon_{y}^{e} = \varepsilon_{y}^{p} = 0$

$$W_D = 0$$
, $S = 0$; entropy of heat reservoir, $S_R = 0$

Along OA (Figs. 3 & 4)

$$d\epsilon_x = d\epsilon_x^e = d\sigma_x/(\lambda + 2\mu)$$

$$d\sigma_{V} = \lambda d\sigma_{X}/(\lambda + 2\mu)$$

$$d\varepsilon_{x}^{p} = d\varepsilon_{v}^{p} = dW_{p} = d\varepsilon_{v}^{e} = 0$$

$$dW_n = 0$$

Along AB

$$\sigma_{x} - \sigma_{y} = -Y;$$
 $d(\sigma_{x} - \sigma_{y}) = -dY = 2\mu(d\epsilon_{x}^{e} - d\epsilon_{y}^{e}) = 0$

$$d\epsilon_y^e = d\epsilon_x^e$$

$$d_{\varepsilon_X} = d_{\varepsilon_X}^e + 2d_{\varepsilon_Y}^e = 3d_{\varepsilon_X}^e$$

$$d\sigma_{X} = 3\lambda d\varepsilon_{X}^{e} + 2\mu d\varepsilon_{X}^{e}$$

$$d\epsilon_{\chi}^{e} = d\sigma_{\chi}/(3\lambda + 2\mu)$$

$$d\varepsilon_{x} = 3d\varepsilon_{x}^{e} = 3d\sigma_{x}/(3\lambda + 2\mu)$$

$$d\epsilon_{x}^{p} = d\epsilon_{x} - d\epsilon_{x}^{e} = 2d\epsilon_{x}^{e}$$

$$dW_{p} = 2V_{\tau}d_{\varepsilon_{X}}^{p} = -VYd_{\varepsilon_{X}}^{p}$$

$$V = V_0 \exp(\epsilon_X)$$

$$d\sigma_y = d\sigma_x$$

$$d\varepsilon_y^p = -d\varepsilon_y^e = -d\varepsilon_{x'}^e$$

dS (reservoir) = -dS (sample) +
$$dW_{D}/T$$

Along BC

$$d\varepsilon_{X} = d\varepsilon_{X}^{e} = d\sigma_{X}/(\lambda + 2\mu)$$

$$d\sigma_y = \lambda d\sigma_x/(\lambda + 2\mu)$$

$$d\varepsilon_{x}^{p} = d\varepsilon_{y}^{p} = d\varepsilon_{y}^{e} = 0$$

$$dW_p \approx 0$$

Aong CF

$$\sigma_{x} - \sigma_{y} = Y$$
 $d\varepsilon_{y}^{e} = d\varepsilon_{x}^{e}$

$$d\epsilon_{\chi} = 3d\epsilon_{\chi}^{e} = 3d\sigma_{\chi}/(3\lambda + 2\mu)$$

$$d\epsilon_{x}^{p} = 2d\epsilon_{x}/3$$

$$d\varepsilon_y^p = -d\sigma_\chi/(3\lambda + 2\mu)$$

$$d\sigma_y = d\sigma_x$$

$$dW_p = VY d\epsilon_X^p$$

dS (reservoir) = -dS (sample) +
$$dW_p/T$$

Along FO

$$d\varepsilon_{X} = d\varepsilon_{X}^{e} = d\sigma_{X}/(\lambda + 2\mu)$$

$$d\sigma_y = \lambda d\sigma_X/(\lambda + 2\mu)$$

$$d\varepsilon_x^p = d\varepsilon_y^p = d\varepsilon_y^e = 0$$

$$dW_p = 0$$

At 0

$$\varepsilon_{X} = 0, \quad \sigma_{X} = 0$$

Compressive stress at B: assume $\sigma_x^B = -40.6 \text{ kb}$

$$\sigma_{x}$$
, σ_{y}

at A:
$$\sigma_{x} - \sigma_{y} = [1 - \lambda/(\lambda + 2\mu)]\sigma_{x} = -Y$$

$$\sigma_{x}^{A} = -(\lambda + 2\mu)Y/2\mu = -20.6 \text{ kb}; \quad \sigma_{y}^{A} = -10.6 \text{ kb}$$
at B: $\sigma_{x}^{B} = -40.6 \text{ kb}$ (assumed), $\sigma_{y}^{B} = -30.6 \text{ kb}$

at B:
$$\sigma_{x} = \frac{-40.6 \text{ kb}}{40.6 \text{ kb}}$$
 (assumed), $\sigma_{y} = -30.6 \text{ kb}$

at C:
$$\sigma_{X}^{C} - \sigma_{y}^{C} = Y$$

$$\sigma_{X}^{C} - \sigma_{y}^{C} - (\sigma_{X}^{B} - \sigma_{y}^{B}) = (\sigma_{X}^{C} - \sigma_{X}^{B}) - (\sigma_{y}^{C} - \sigma_{y}^{B})$$

$$= (\sigma_{X}^{C} - \sigma_{X}^{B}) [1 - \lambda/(\lambda + 2\mu)] = 2Y$$

$$\sigma_{X}^{C} - \sigma_{X}^{B} = Y(\lambda + 2\mu)/\mu = 41.2 \text{ kb}$$

$$\sigma_{X}^{C} = 0.6 \text{ kb}$$

$$\sigma_{Y}^{C} = -9.4 \text{ kb}$$

<u>at F</u>: $\sigma_X^F - \sigma_y^F = Y$ whether the point F is reached by expanding along the elastic isotherm, OF, or along the plastic curve, CF. In the former case,

$$\frac{\sigma_x^F = -\sigma_x^A = 20.6 \text{ kb.}}{\text{Then } \sigma_y^F = 10.6 \text{ kb.}}$$

Both $\sigma_{\rm X}$ and $\sigma_{\rm V}$ return to zero since both have their elastic values at F.

$$\frac{\varepsilon_{X}}{\varepsilon_{X}} = \sigma_{X}^{A}/(\lambda + 2\mu) = -.01823$$

$$\begin{split} \varepsilon_{X}^{\ B} &= \varepsilon_{X}^{\ A} + 3(\sigma_{X}^{\ B} - \sigma_{X}^{\ A})/(3\lambda + 2\mu) = -.01823 - .02616 = -.04439 \\ \varepsilon_{X}^{\ C} &= \varepsilon_{X}^{\ B} + (\sigma_{X}^{\ C} - \sigma_{X}^{\ B})/(\lambda + 2\mu) = -.04437 + .03646 = -.00793 \\ \varepsilon_{X}^{\ F} &= \varepsilon_{X}^{\ C} + 3(\sigma_{X}^{\ F} - \sigma_{X}^{\ C})/(3\lambda + 2\mu) = -.00793 + .026155 = +.01823 \\ \varepsilon_{X}^{\ O} &= 0 \\ &\frac{\varepsilon_{X}^{\ E}}{\varepsilon_{X}^{\ E}} \\ &\varepsilon_{X}^{\ E}(A) &= \varepsilon_{X}^{\ A} = -.01823 \\ \varepsilon_{X}^{\ E}(B) &= \varepsilon_{X}^{\ E}(A) + (\sigma_{X}^{\ B} - \sigma_{X}^{\ A})/(3\lambda + 2\mu) = -.01823 - .00871 = -.02694 \\ \varepsilon_{X}^{\ E}(C) &= \varepsilon_{X}^{\ E}(B) + (\sigma_{X}^{\ C} - \sigma_{X}^{\ B})/(\lambda + 2\mu) = -.02694 + .03646 = .00952 \\ \varepsilon_{X}^{\ E}(F) &= \varepsilon_{X}^{\ E}(C) + (\sigma_{X}^{\ F} - \sigma_{X}^{\ C})/(3\lambda + 2\mu) = .00952 + .00871 = .01823 \\ \varepsilon_{X}^{\ E}(O) &= 0 \end{split}$$

$$\frac{\varepsilon_{x}^{p}}{\Xi_{x}}$$

$$\varepsilon_{x}^{p}(A) = \underline{0}$$

$$\varepsilon_{X}^{p}(B) = 2(\sigma_{X}^{B} - \sigma_{X}^{A})/(3\lambda + 2\mu) = -.017428$$

$$\varepsilon_{X}^{p}(C) = \varepsilon_{X}^{p}(B)$$

$$\varepsilon_{Y}^{p}(F) = \varepsilon_{Y}^{p}(C) + 2(\sigma_{X}^{F} - \sigma_{X}^{C})/(3\lambda + 2\mu) = \underline{0} = \varepsilon_{X}^{p}(0)$$

$$\frac{\varepsilon_y^e}{\varepsilon_y^e}$$

$$\varepsilon_y^e(A) = \underline{0}$$

$$\varepsilon_y^e(B) = (\sigma_x^B - \sigma_x^A)/(3\lambda + 2\mu) = \underline{-.008714}$$

$$\varepsilon_{y}^{e}(C) = \varepsilon_{y}^{e}(B)$$

$$\varepsilon_{y}^{e}(F) = \varepsilon_{y}^{e}(C) + (\sigma_{x}^{F} - \sigma_{x}^{C})/(3\lambda + 2\mu) = \underline{0} = \varepsilon_{y}^{e}(0)$$

$$\frac{\varepsilon_y^p = -\varepsilon_y^e}{}$$

$$y^e = (\varepsilon_x^e - \varepsilon_y^e)/2$$

$$\gamma^{e}(A) = -.01823/2 = -.00911$$

$$\gamma^{e}(B) = -.00911$$

$$_{\gamma}^{e}(c) = +.00911$$

$$_{Y}^{e}(F) = .00911$$

$$_{\gamma}^{e}(0) = 0.0$$

$$W_{D}(A) = 0.0$$

$$W_p(B) = -(2YV_0/3) [exp(\epsilon_x^B) - exp(\epsilon_x^A)] = .0625$$

$$W_p(C) = W_p(B)$$

$$W_p(F) = W_p(B) + (2YV_0/3) [exp(\epsilon_X^F) - exp(\epsilon_X^C)] = .0625 + .0648 = .1273$$

Computation of Entropy

From Eqs. (66) - (68) changes in entropy of the sample are given by

$$dS = rC_V d\epsilon_X - (16V/3) (\partial_{\mu}/\partial_{\Gamma})_{\gamma}^{e} V^{e} d\gamma^{e} .$$

From Eq. (35), $d\gamma^e = d\tau/2\mu$.

From Appendix J, for aluminum

$$-(\partial \mu/\partial T)_{V,\gamma}e^{\simeq}.14 \text{ kb/°C} \text{ at } 300^{\circ}\text{K}.$$

From Eq. (75a), $V(\partial \mu/\partial T)$ is constant. For $V = V_0 = .37cc/g$, we have

$$-(16V/3)(\partial \mu/\partial T)_{e,V} \simeq .27 \text{ kb cc/g}^{\circ}C.$$

For $\Gamma = 2$, $C_V = 8.4 \times 10^{-3}$ kb cc/g°C, we get

dS =
$$(16.8 \times 10^{-3} d_{\epsilon_{x}} + .27 \gamma^{e} d_{\gamma}^{e})$$
 kb cc/g°C.

From 0 to A, $d_{\gamma}^{e} = d_{\epsilon_{\chi}}/2$ and $\gamma^{e} = \epsilon_{\chi}/2$, so at A

$$S(A) = 16.8 \times 10^{-3} \epsilon_{x}(A) + .03375 \epsilon_{x}^{2}(A) = -2.950 \times 10^{-4}$$

On AB, $d_Y^e = 0$, so

$$S(B) = S(A) + 16.8 \times 10^{-3} [\epsilon_x(B) - \epsilon_x(A)] = -7.345 \times 10^{-4}$$

From B to C $d_Y^e = d_{\varepsilon_X}/2$ but $Y_Y^e \neq \varepsilon_X/2$, so it is simpler to retain Y_Y^e .

Thus

$$dS = 16.8 \times 10^{-3} d_{\varepsilon_{X}} + .135 d_{(\gamma^{e})^{2}}$$

$$S(C) = S(B) + 16.8 \times 10^{-3} [\varepsilon_{\chi}(C) - \varepsilon_{\chi}(B)] + .135[\gamma^{e^{2}}(C) - \gamma^{e^{2}}(B)] = -1.220 \times 10^{-4}$$

From C to F $d_Y^e = 0$, so

$$S(F) = S(C) + 16.8 \times 10^{-3} [\epsilon_{x}(F) - \epsilon_{x}(C)] = 3.175 \times 10^{-4}$$

Finally at 0

$$S(0) = S(F) + 16.8 \times 10^{-3} \left[\varepsilon_{X}(0) - \varepsilon_{X}(F) \right]$$

$$+ .135 \left[\left(\gamma^{e} \right)^{2} (0) - \left(\gamma^{e} \right)^{2} (F) \right] = \underline{4.68 \times 10^{-9} \approx 0.0}$$

Entropy of the Reservoir

$$S_{R}(A) = -S(A) = 2.950 \times 10^{-4}$$

 $S_{R}(B) = S_{R}(A) - (S_{B} - S_{A}) + W_{p}(B)/300 = \underline{9.429 \times 10^{-4}}$
 $S_{R}(C) = S_{R}(B) - (S_{C} - S_{B}) = \underline{3.303 \times 10^{-4}}$
 $S_{R}(F) = S_{R}(C) - [S_{F} - S_{C}] + [W_{p}(F) - W_{p}(C)]/2 = \underline{1.068 \times 10^{-4}}$
 $S_{R}(0) = S_{R}^{F} - (S_{0} - S_{F}) = \underline{4.243 \times 10^{-4}}$

TABLE D-1. Values of mechanical and thermal variables at various points on the cycle of Fig. 4. Calculated from Program "CYCLE." Columns

A, B, etc. correspond to points A, B, etc. in Fig. 4. First entry in each box: Isothermal cycle, T = 300°K Third entry in each box: Isentropic cycle, S = 0

Fourth entry in each box: Adiabatic cycle

The entropy in parenthesis is obtained from exact integration as described in the first part of this Appendix.

	Α	В	С	F	0
σx .	-20.6206 (-20.6) -20.5921	-40.6000 (-40.6) -40.6000	.642331 (0.6) .461812 .380745	20.6192 (20.6) 20.6454 20.3785	0.0 (0.0) 0.0
σy	-10.6206 (-10.6) -10.5921	-30.6001 (-30.6) -30.6001	-9.35767 (-9.4) -9.53819 -9.61926	10.6193 (10.6) 10.6455 10.3786	000496 (0) 000089 096066
p	13.9540	33.9334	6.02433	-13.9526	.000330
	13.9254	33.9334	6.20485 6.28592	-13.9788 -13.7119	.000059 .064044
٧	.363308	.353937	. 367091	.376806	.369991
	.363308	.353852 .353837	.367002 .366987	.376806 .376736	.369991 .369987
εx	0182483 (01823) 0182482	0443763 (04439) 0446184 0446597	00787783 (00793) 00812133 00816250	.0182470 (.01823) .0182478 .0180612	-4 x 10 ⁻⁸ (0.0) 1 x 10 ⁻⁸ -1.1 x 10 ⁻⁵
γ ^e	00912418 (009113) 00912413	00912418 (009113) 00912413	.00912448 (.009117) .00912403 .00912406	.00912448 (.009117) .00912403 .00912406	$.9 \times 10^{-6}$ (0.0) 1×10^{-7} $.88 \times 10^{-4}$
εx	0.0 (0.0) 0.0	0174187 (017428) 0175801 0176076	0174187 (017428) 0175801 0176076	-2 x 10 ⁻⁶ (0.0) -6 x 10 ⁻⁷ 000125060	-2 x 10 ⁻⁶ (0.0) -6 x 10 ⁻⁷ -1.3 x 10 ⁻⁴
ε X	0182483 (01823) 0182482	0269576 (02694) 0270382 0270520	.00954075 (.00952) .00945874 .00944509	.0182490 (.01823) .0182484 .0181863	2×10^{-6} $(0.0)_{7}$ 6×10^{-4} 1.1×10^{-4}

TABLE D-1 -- Continued

	A	B	C	F	0
· e εy	0.0 (0.0) 0.0	00870935 (008714) 00879006 00880379	00870935 (008714) 00879006 00880379	-1×10^{-6} (0.0) -3×10^{-7} -6.25×10^{-4}	-1×10^{-6} (0.0) -3×10^{-7} -6.2×10^{-5}
S	000306570 (000295) 0.0	000745514 (000735) 0.0 +.000195374	000132340 (000122) 0.0 .000195374	.000306558 (.000317) 0.0 .000406573	7 x 10 ⁻⁹ (5 x 10 ⁻⁹) 0.0 .000406573
М _р	0.0 (0.0) 0.0	.0624640 (.0625) .0630353 .0631326	.0624640 (.0625) .0630353 .0631326	.127240 (.1273) .128409 .128138	.127240 (.1273) .128409 .128138
T	300 (300) 311.145	300 (300) 327.989 335.734	300 (300) 304.891 312.090	300 (300) 289.223 303.679	300 (300) 299.966 314.849

Program CYCLE

In the general case where λ , μ , Y may be functions of density and temperature, numerical integration of the preceding equations may be required. This can be accomplished with the FORTRAN program described here. With it one can obtain values of the variables listed above for isothermal, isentropic or adiabatic cycles. The last of these is a cycle only in the sense that stress returns to its original value. The other variables do not because plastic work is retained in the sample.

Results of integrations for conditions described in the first part of this Appendix are listed in Table D-1 for the vertices ABCFO. For isothermal and isentropic cases the cyclic variables do not quite return to zero. These integrations are accomplished by a direct, approximately second-order integration scheme. The listed values were obtained with $d\sigma_{\chi} = -.406$ kb; reducing it to a half or a third of this value did not significantly improve the closing values. For greater accuracy a better integration scheme would be required.

The following assumptions are made about the equation of state: bulk modulus:

where
$$K_0 = \text{isothermal bulk modulus at } T = T_0$$
, $p = 0$

$$b = \text{polytropic coefficient, i.e. } p(T_0, V) = (K_0/b)[(V_0/V)^b - 1]$$

$$\delta = \beta - \alpha K_0 b$$

$$\alpha = \text{thermal expansion coefficient, } (1/V)(\partial V/\partial T)_p$$

$$\beta = C_V(\Gamma_0 + \Gamma_1)/V_0$$

$$C_V = \text{specific heat at constant volume}$$

$$V_0 = \text{specific volume at } T = T_0, p = 0$$

$$\Gamma = \text{Gruneisen parameter} = \Gamma_0 + \Gamma_1(1 - V/V_0)$$

 $g = (\beta/3K_0) (4-1/b) - \alpha b^2$

$$\mu = \mu_0 + b_1 (T/V - T_0/V_0)$$

 T_0 = const. is a reference temperature

For aluminum these constants are approximately

$$\Gamma_{\rm o}$$
 = 2.14, $\Gamma_{\rm l}$ = -3.2, $C_{\rm V}$ = 8.4 x 10⁻³ kb cc/g°K, $V_{\rm o}$ = .37 cc/g α = .75 x 10⁻⁴/°K, $K_{\rm o}$ = λ + $2\mu/3$ = 764.67 kb

$$\lambda = 582 \text{ kb}, \quad \mu_0 = 274 \text{ kb}, \quad T_0 = 300^{\circ} \text{K}$$

$$\beta = -.024065 \text{ kb/°K}, \quad \delta = -.26895 \text{ kb/°K}$$

$$g = -1.40697 \times 10^{-3} / ^{\circ} K$$
, $b = 4.27$

Provision is also made for introducing work-hardening in an elementary way. The yield strength can vary with plastic work according to the relation

$$Y = Y_0 + A[1 - \exp(W_p/W_0)]$$

where Y_0 , A and W_0 are constants.

Comments on the Program Listing

- IC is the integer index which determines whether the computation will be made under isothermal, isentropic or adiabatic conditions.
- N The stress increment used in integration is σ_{x}^{B}/N where $-\sigma_{x}^{B}$ is the maximum compressive stress to be reached.
- MM This is the number of cycles to be calculated. For this run two cycles are calculated. IC = 2 for the first and IC = 3 for the second. IC is incremented by card number 0184 (left hand column).

$$V \otimes \emptyset = V_{\Omega}$$

$$TØ = T_0$$

$$KØ = K_{\Omega}$$

$$GAMO = r_0$$

$$GAM7 = \Gamma_7$$

$$CV = C_{V}$$

$$MUØ = \mu_0$$

BETA =
$$\beta$$

$$DELTA = \delta$$

$$SGAM = g$$

$$AMU = b_1$$

$$A = A$$

$$WØ = W_{\Omega}$$

SIGXB =
$$\sigma_x^B$$
 = -(compressive stress at which stress cycle is reversed)

MCOUNT = integer index which counts the number of cycles. It is incremented by 1 at the end of each cycle.

V(J) = specific volume for J^{th} increment in stress

$$EPX = \epsilon_{x}$$

$$EPY = \epsilon_y$$

EXE =
$$\epsilon_x^e$$

EYE =
$$\epsilon_v^e$$

$$EPXP = \epsilon_{x}^{p}$$

$$EPYP = \epsilon_{v}^{p}$$

$$S(J) = entropy$$

$$MU = \mu$$

$$LAM = \lambda$$

$$YB = \overline{Y}$$

WPB =
$$\overline{W}_{D}$$

 $TB = \overline{T}$ These quantities indicated by B or $\overline{}$ are averages of values at the last J and the next J. Their use makes the integration scheme approximately second order.

$$DY = dY$$

ISTOP, IFLAG are control indices used for stopping the calculation and calculating the end of the cycle.

IY is an index used to guide the computation through the elastic branch (IY=1) or elastic-plastic branch (IY=2).

JA = 1 indicates region FOA of Fig. 4.

- = 2 indicates region AB of Fig. 4.
- = 3 indicates region BC of Fig. 4.
- = 4 indicates region CF of Fig. 4.

JM is the index which directs the computation to the next branch of the cycle.

IS is an index used to calculate the end points (A, B, C, F, O) of each branch.

$$GAM = \Gamma$$

The program contains a subroutine for use with a CALCOMP plotter. It is by-passed in this listing, but it can be engaged by removing card number 0233, "GØ TØ 99."

Following the listing is sample output for the two cases shown in Table D-1 for isentropic and adiabatic compression.

							4	1	
							,		
•						•			
		· · · · · · · · ·					4	T.	
							1	:	•
		er tree e .			ű.		. 4.		
						•		, ,	æ
						•			₹
						•		*	
			•						
		•							
							•		
			•	•					
						•			
				•					
•									
								•	
								•	
	•								Ģ
							,		
									2
		•							
						:			
						·			
	•					•			

PROGRAM "CYCLE"

 ∞

							*	
					,			
		,			·			·
÷ .								
	• .							
			,	٠				- g-w - - w
·	•,					•)	4)	

```
ည္သ
```

```
FORTRAN IV G LEVEL 20
                                        MAIN
                                                           DATE = 72332
                                                                                 15/18/08
 0001
                   DIMENSION SIGX(1500), SIGY(1500), EPX(1500), EPY(1500), EXE(1500)
                                                                                        P.001
 0002
                   DIMENSION EYE(1500), EPXP(1500), EPYP(1500), WP(1500), Y(1500)
                                                                                        R002
 0003
                   DIMENSION P(1500), V(1500), J1(1500)
                                                                                        R003
 0004
                   DIMENSION T(1000)
                  DIMENSION S(1000), GAMME(1000)
 0005
 0006
                   REAL K. KO, MU, LAM, MUO, MUI, MU2
 0007
                   REAL JI, LENGX, LENGY
                                                                                        R005
0008
                   INTEGER PENP
                                                                                        R005AAA
 0009
                   DATA XEPX/' EPX'/, XEXE/' EXE'/, XEYE/' EYE'/
                                                                                        ROO 5AA
0010
                   DATA XJ1/ J '/,XSIGX/'SIGX'/.XSIGY/'SIGY'/,XEPXP/'EPXP'/
                                                                                        ROC5A
             C
             C KO.K.LAM.MU.MUO
                                    ARE IN KILOBARS
             C B IS DIMENSIONLESS
             C BETA IS IN KILOBARS/DEGREE C. BEAT=CV*(GAMO+GAM1)/VOO
             C CV IS IN KB-CC/GRAM-DEGREE C.
             C V, VOO ARE IN CC/G
             C GAM, GAMO, GAMI ARE DIMENSIONLESS
             C DELTA IS IN KILOBARS/DEGREE C
             C DELTA = - (ALPHA*KO*8-BETA)
             C ALPHA = VOLUME EXPANSION COEFFICIENT, (DEG C) **-1, =. 75E-4 FOR AL
             C K=ISDTHERMAL BULK MODULUS
             C LAM AND MU ARE LAME! CONSTANTS
             C SGAM IS IN (DEG C)**-1, SGAM=(4*BETA/3KO-BETA/(3*KO*B)-ALPHA*(BETA)**2
             C IY=1' IF COMPRESSION (OR EXPANSION) IS ELASTIC
             C IY=2 IF COMPRESSION IS ELASTIC-PLASTIC
             C IC=1 FOR ISOTHERMAL PROCESS
             C IC=2 FOR ISENTROPIC PROCESS
             C IC=3 FOR ADIABATIC PROCESS
             C
                   CONSTANTS
                                                                                        R006
                   ALUMINUM
                                                                                        R007
0011
                   IC=1
C012
                   N = 100
0013
                   MM=2
```

```
85
```

```
0048
                    K=K0
                                                                                                 R032
0049
                    MU=MUO
CC50
                    LAM=K-(2./3.)*MU
0051
                    YB=YO
0052
                    WPB=WP(1)
0053
                    TB=T(1)
0054
                    DY=0.
0055
                    VB=V00
0056
                    ISTOP=1
0057
                    IFLAG=1
0058
                400 CONTINUE
              CCC
                    ALONG DA
                                                                                                R036
0059
                    WRITE(6,101)
0060
                101 FORMAT(4X, "J", 8X, "SIGX", 11X, "SIGY", 13X, "P", 14X, "Y", 14X, "V", 11X,
                   + * EPX * , 11X + * GAMME * )
              C
0061
                    WRITE(6,102)
0062
                    J=1
                                                                                                R037
0063
                301 CONTINUE
0064
                    [Y=1
0065
                    JA = 1
0066
                    JM = 2
0067
                    IS=1
0068
                    GD TO 201
0069
                302 CONTINUE
0070
                    IY=2
C071
                    J\Lambda = 2
0072
                    JM=3
0073
                    IS=1
0074
                    GD TO 201
CC75
                303 CONTINUE
0076
                    [Y=1
0077
                     JA=3
0078
                     JM=4
```

```
DSIGX=-DSIGX
0079
                   I S=1
0080
                  GD TD 201
0081
               304 CONTINUE
0082
                   1Y=2
0083
                   JA=4
CC84
                   JM=1
CC85
                   TS≠1
0086
                   DSIGX=-DSIGX
0087
                   SIGXT=0.0
0088
0089
               201 CONTINUE
                                                                                         R039
                 1 SIGX(J+1)=SIGX(J)+DSIGX
0090
            C
                   IF(IFLAG.EQ.2.AND.SIGX(J+1)-LT.0.0) GO TO 2
0091
C092
                   GO TO 3
                 2 CONTINUE
0093
                   DSIGX=-SIGX(J)
0094
                   IFLAG=1
C095
                   ISTOP=2
0096
                   WRITE(6,110)
0097
               110 FORMAT(2X, "NEXT VALUES COMPLETE THE CYCLE")
0098
0099
                   GO TO 1
                 3 CONTINUE
0100
               COMPUTE SIGY(J+1)
                                                                                         R041
                   DO 8 M=1,3
0101
                   GD TO (41,42), IY
0102
                41 DSIGY=LAM*DSIGX/(LAM+2.*MU)
0103
0104
                   GO TO 43
                42 DSIGY=DSIGX+DY
0105
                   IF(JA.EQ.4) DSIGY=DSIGX-DY
C106
                43 CONTINUE
0107
                   SIGY(J+1) = SIGY(J)+DSIGY
0108
                   P[J+1] =- (SIGX(J+1)+2. *SIGY(J+1))/3.
0109
                   PB=(P(J+1)+P(J))/2.
0110
                                                                                         R046
                   DP = P(J+1) - P(J)
0111
                   K=KO+B*PB+(DELTA+SGAM*PB)*(IB-TO)
0112
```

```
0113
                   DV=-VB*DP/K
                                                                                           R048
0114
                   DEPX=-DP/K
                                                                                           R047
0115
                   V(J+1)=V(J)+DV
                                                                                           R049
0116
                   VB = V(J) + DV/2
0117
                   MU=MUO+AMU*(TB/VB-TO/VOO)
0118
                   LAM=K-(2./3.)*MU
               COMPUTE PLASTIC WORK AND Y
0119
                   GO TO (51,52), IY
0120
                51 DWP=0.
                   DY=0.
0121
0122
                   GO TO 53
0123
                52 CONTINUE
0124
                   IF (JA.EQ.4) YB=-YB
0125
                   IF(JA.EQ.4)DY=-DY
0126
                   DWP=-(2.*VB*YB/3.)*(DEPX+DY/(2.*MU))
0127
                   DY=(A/WO)*DWP*EXP(-WPB/WO)
                53 CONTINUE
0128
0129
                   WP (J+1)=WP(J)+DWP
                                                                                           R086
0130
                   WPB=(WP(J+1)+WP(U))/2.
                                                                                           R087
0131
                   Y(J+1)=Y(J)+DY
                                                                                           R085
0132
                   YB = (Y(J+1)+Y(J))/2.
                                                                                           R140
                COMPUTE GAMMA-ELASTIC
0133
                   DGAMME=(DSIGX-DSIGY)/(4.*MU)
0134
                   GAMME(J+1)=GAMME(J)+DGAMME
0135
                   GAMMEB = GAMME ( J ) + DGAMME / 2.
             C COMPUTES S AND T
```

```
GAM=GAMO+GAM1*(1.-V8/VOO)
0136
                  GD TO (31.32.33), IC
0137
                31 DT=0
0138
                  DS=GAM+CV*DV/VB-16.*GAMMEB*AMU*DGAMME/3.
0139
                   GO TO 34
0140
0141
               32 DS=0
                  DT=-GAM*TB*DV/VB+16.*GAMMEB*TB*AMU*DGAMME/(3.*CV)
0142
                   GO TO 34
0143
                33 DS=DWP/TB
0144
                   DT=TB+DS/CV-GAM+TB+DV/VB+16=+GAMMEB+TB+AMU+DGAMME/(3=+CV)
0145
                34 T(J+1)=T(J)+DT
0146
                   S(J+1)=S(J)+DS
0147
0148
                   TB=T1J)+DT/2.
               102 FORMAT (15x, "EPXP", 12x, "EPXE", 10x, "EPYE", 13x, "S", 15x, "WP", 10x, "T")
0149
                 8 CONTINUE
0150
                  GO TO (61.62).IY
0151
              COMPRESSION IS ELASTIC
0152
               61 DEPXP=0.
                  DEPXE=DEPX
0153
                  DEPYP=0.
0154
                  DEPYE=0.
0155
                  GO TO 63
0156
            C COMPRESSION IS ELASTIC-PLASTIC
               62 CONTINUE
0157
                  DEPXP=(2./3.)*(DEPX+DY/(2.*MU))
0158
                                                                                         R093
0159
                   DEPXE=DEPX-DEPXP
                  DEPYP=-DEPXP/2.
0160
0161
                   DEPYE = - DEPYP
               63 CONTINUE
0162
```

```
0163
                   EPX(J+1)=EPX(J)+DEPX
0164
                   EPXP(J+1)=EPXP(J)+DEPXP
0165
                   EXE(J+1)=EXE(J)+DEPXE
0166
                   EPYP(J+1) = EPYP(J) + DEPYP
0167
                   EYE(J+1)=EYE(J)+DEPYE
0168
                   J=J+1
0169
                   WRITE(6,104) J, SIGX(J), SIGY(J), P(J), Y(J), V(J), EPX(J), GAMME(J)
0170
               104 FORMAT(2X,14,5F15.8,2E15.6)
0171
                   WRITE(6,105)EPXP(J),EXE(J),EYE(J),S(J),WP(J),T(J)
0172
               105 FORMAT(10x,5E15.6,F15.8)
0173
                   IF(J.GT.999)GO TO 21
0174
                   IF(IS.EQ.2)DSIGX=SIGXB/Q
0175
                   IF(IS-EQ.2) GO TO 76
0176
                   GO TO (71.72.73.74).JA
0177
                71 CONTINUE
0178
                   IF(ISTOP-EQ.1)GO TO 5
0179
                   IF (MCOUNT.GT.MM)GO TO 21
0180
                 4 CONTINUE
0181
                   J = I
0182
                   ISTOP=1
0183
                   IFLAG=1
0184
                   IC=IC+1
0185
                   IF11C-GT-31GO TO 21
0186
                   DSIGX=SIGXB/O
0187
                   GD TO 400
0188
                 5 CONTINUE
0189
                   IF ((SIGX(J)-SIGY(J)).GT.-Y(J)) GO TO 201
0190
                   ZN=SIGX(J)-SIGY(J)
0191
                   ZO=SIGX(J-1)-SIGY(J-1)
0192
                   DZ = ZN - ZO
0193
                   DSIGX = -(DSIGX/DZ) * (Y(J-1) + ZO) / (1.-DY/DZ)
0194
                   J = J - 1
0195
                   IS=IS+1
                   WRITE(6,106)
0196
0197
               106 FORMAT(10x, NEXT VALUES ARE FOR POINT A)
0198
                   GO TO 201
                72 IF(SIGX(J).GT.SIGXB) GO TO 201
0199
0200
```

DSIGX=SIGXB-SIGX(J-1)

R091

R090

R094

R096

R097

```
0201
                    IS=IS+1
 0202
 0203
                    WRITE(6,107)
                107 FORMAT(10X, NEXT VALUES FOR POINT B')
 0204
                    GD TO 201
0205
                 73 IF((SIGX(J)-SIGY(J)).LT.Y(J1) GO TO 201
 0206
                    ZN=SIGX(J)-SIGY(J)
 0207
                    ZO = SIGX(J-1) - SIGY(J-1)
 0208
 0209
                    DZ = ZN - ZO
                    DSIGX = \{DSIGX/DZ\} * (Y(J-1)-ZO)/(1.-DY/DZ)
 0210
 0211
                    J=J-1
0212
                    IS=IS+1
 0213
                    WRITE (6.108)
                108 FORMATIIOX, NEXT VALUESFOR POINT CO)
 0214
                    GO TO 201
 0215
                 74 IF(EPX(J).LT.0.0) GO TO 201
 0216
                    IF(EPX(J-1).LT.O.O) DEPX=EPX(J)
 0217
                    DSIGXT=(LAM+2.*MU)*DEPX
 0218
                    SIGXT=SIGXT+DSIGXT
0219
                    IF(SIGXT.LT.SIGX(J)) GO TO 201
 0220
                    DSIGX=(DSIGX/DSIGXT)*(SIGX(J-1)-SIGXT+DSIGXT)/(1.-DSIGX/DSIGXT)
 0221
                    J=J-1
 0222
                    IS=IS+1
 0223
                    WRITE(6,109)
 0224
               109 FORMAT(10X, NEXT VALUES FOR POINT F.)
 0225
 0226
                    IFLAG=2
                                                                                           R160
                    MC OUNT = MC DUNT+1
 0227
 0228
                    GO TO 201
                 76 CONTINUE
0229
                    GO TO 1301,302,303,304),JM
 0230
                                                                                           R162
 0231
                 21 CONTINUE
 0232
                 55 CONTINUE
                    GO TO 99
 0233
                 56 CONTINUE
 0234
                                                                                           R163
                   .DD 20 K2=1,J
```

J=J-1

90

		_
۹	s	_
	Ξ	_

· ·		
0236	20 J1(K2)=K2	R164
0237	ZERO=1.0	R165
0238	LENGX=4.5	R166
0239	LENGY=LENGX	R167
0239	NCHARX=4	R168
0240	NC HARY=NCHARX	•
0241	PLEND=7.0	R169
0242	PEND=7.0 PENP=-3	R170
0244		R171
0245	ORIGIN=0.0	R172
0245	FACT=1.0	P173
0240	CALL PLOTITIJ1, SIGX, LENGY, NCHARX	
03/7	C, J, PENP, ORIGIN, FACT)	R175
0247	CALL PLOTITIJI, SIGY, LENGY, NCHARX	· · · · · · · · · · · · · · · · · · ·
634.0	C, J, PENP, ORIGIN, FACT)	R177
0248	CALL PLOTITIJI, EPXP, LENGX, LENGY, NCHARX	•
0040	C.J.PENP.ORIGIN.FACT)	R179
0249	CALL PLOTIT(J1, EPX, LENGX, LENGY, NCHARX,	
0050	C, PENP, ORIGIN, FACT)	R181
0250	CALL PLOTIT(J1, EXE, LENGX, LENGY, NCHARX,	NCHARY, XJ1, XEXE, PLEND, ZERO, JR182
	C, PENP, ORIGIN, FACT)	R183
0251	PENP=999	R184
0252	PLEND=10.0	R185
0253	CALL PLOTIT(J1, EYE, LENGX, LENGY, NCHARX,	NCHARY, XJ1, XEYE, PLEND, ZERO, JR186
	C, PENP, ORIGIN, FACT)	R187
0254	99 STOP	R188
0255	END	R189

P g

0002

0003

FORTRAN IV G LEVEL 20

SUBROUTINE PLOTIT(X,Y,LENGX,LENGY,NCHARX,NCHARY,TITLEX,TITLEY,PLENS100 CD,ZERO,NPTS,PENP,ORIGN.FCTR) S101 DIMENSION IBUF(1500),X(1500),Y(1500) S102 REAL*8 TITLEX,TITLEY S103 REAL LENGX,LENGY S104 INTEGER PENP S105 DATA ENTER/1./

INSTRUCTIONS FOR USING THE PLOT SUBROUTINE:

THE TITLES FOR THE PLOTS MUST BE LITERAL CONSTANTS NO LONGER THAN EIGHT CHARACTERS IN LENGTH AND MUST BE DECLARED REAL *8.

FOR THE CASE OF TOTALLY POSITIVE DATA THE SCALE ROUTINE WILL RETURN A NON-ZERO ORIGIN FOR ONE OR BOTH AXES. IF A ZERO ORIGIN IS DESIRED FOR BOTH AXES THE VARIABLE ORIGN SHOULD BE SET TO ZERO AND FOR NON-ZERO ORIGINS ORIGN SHOULD BE SET TO ONE.

CONTINUE

IN CALLING THE SUBROUITNE THE VALUE ASSIGNED TO THE VAR-IABLE ZERO SHOULD BE NO SMALLER THAN .5 SINCE ANYTHING SMALLER WOULD NOT ALLOW ROOM TO PRINT THE TITLE FOR THE X-AXIS.

CARE MUST BE TAKEN IN CHOOSING THE VALUES FOR THE VARIABLE LENGY. THE SUM OF LENGY AND ZERO SHOULD NOT EXCEED 10.
THE WIDTH OF THE PLOTTING PAPER IS ONLY 11 INCHES AND THE
VALUE FOR ZERO TELLS THE PLOTTER HOW FAR ABOVE THE BOTTOM OF
THE PAPER TO BEGIN DRAWING THE Y-AXIS, THEREFORE THE AXIS MUST
BE SHORT ENOUGH TO FIT ON THE PAPER WITHOUT HITTING THE LIMIT
SWITCH ON THE TOP.

THE VARIABLE FCTR IS USED TO CHANGE THE SIZE OF THE PLOTS WITHOUT CHANGING THE LENGTH OF THE AXES. IT PRODUCES A PLOT WHICH IS A SCALED REPRESENTATION OF THE NORMAL PLOT. IF FCTR IS NOT EQUAL TO ONE CARE MUST BE TAKEN TO INSURE THE NEW PLOT WILL NOT BE TOO LARGE TO FIT ON THE PAGE OR TOO CLOSE TO THE

0009

BOTTOM LIMIT SWITCH. A PLOT MADE VERY SMALL BY THE USE OF THE FCTR PARAMETER MAY NOT BE READABLE, THEREFORE THE USE OF FCTR SHOULD BE LIMITED.

THE VARIABLE PLEND IS THE NUMBER OF INCHES FROM THE ORIGIN THE PEN WILL MOVE IN THE X DIRECTION AT THE END OF THE PLOT. THEREFORE THE VALUE ASSIGNED TO PLEND SHOULD BE THE LENGTH OF THE X-AXIS PLUS THE NUMBER OF INCHES PAST IT THE NEW PLOT IS TO BEGIN. THE VALUE ASSIGNED TO PLEND IN THE FINAL CALL SHOULD BE AT LEAST THE VARIABLE LENGX + 5 TO ALLOW THE PAPER TO BE TORN OFF THE PLOTTER WITHOUT AFFECTING THE PLOT.

CONTINUE

THE VARIABLE PENP SHOULD BE ASSIGNED THE VALUE -3 FOR ALL CALLS TO THE SUBROUTINE EXCEPT THE FINAL CALL. FOR THE FINAL CALL THE VALUE 999 SHOULD BE GIVEN TO PENP. THESE VALUES MERELY RAISE THE PEN WHILE MOVING TO THE NEW ORIGIN, OR FOR THE CASE WHEN PENP=999, WHILE MOVING TO THE END OF THE PAPER.

CONTINUE

X= ARRAY CONTAINING X CODRDINATES Y= ARRAY CONTAINING Y COORDINATES LENGX= LENGTH OF X-AXIS LENGY= LENGTH OF Y-AXIS

NCHARX= NUMBER OF CHARACTERS IN TITLE OF X-AXIS
NCHARY= NUMBER OF CHARACTERS IN TITLE OF Y-AXIS
TITLEX= TITLE TO BE GIVEN X-AXIS
TITLEY= TITLE TO BE GIVEN Y-AXIS
PLEND= DISTANCE PEN WILL MOVE AT END OF PLOT
ZERO= DISTANCE ABOVE BOTTOM OF PAGE PEN SHOULD BE MOVED TO
BEGIN Y-AXIS


	С	NPTS= NUMBER OF POINTS + 2 IN ARRAYS TO BE PLUTTED (NUMBER	
•	. С	OF X POINTS SHOULD EQUAL NUMBER OF Y POINTS. THE TWO	•
	Č	EXTRA PLACES IN THE ARRAYS ARE USED IN THE PLOTTING	
	Č	ROUTINE FOR SCALING)	
	č	PENP= POSITION OF PEN AT END OF PLOT INORMALLY EITHER -3 DR	
	Č	999)	• "
	č	ORIGN= 0.0 FOR ZERO ORIGINS AND 1.0 FOR NON-ZERO ORIGINS	
	č	FCTR= RATIO OF NEW PLOT SIZE TO THE NORMAL PLOT SIZE. A VALUE	
•	Ć	OF 1.0 GIVES PLOTS OF NORMAL SIZE. ANYTHING GREATER	
	č	THAN ONE INCREASES THE SIZE OF THE PLOT WHILE ANYTHING	
	č	LESS THEN DECREASES THE PLOT SIZE	
	C C		
0010	. •	IF(ENTER.NE.1) GO TO 1	5107
0011		CALL PLOTS(IBUF, 1000)	S108
0012	1	ENTER=2.0	S109
0013	-	CALL PLOT(0.0,-11.0,-3)	\$110
0014		CALL FACTOR(FCTR)	\$110
0015		CALL PLOT(0.0, ZERO, -3)	S111
0016		CALL SCALE(X, LENGX, NPTS, 1)	S112
0017		CALL SCALE(Y, LENGY, NPTS, 1)	S113
0018		XPAGE=0.0	S113
0019		YPAGE=0.0	\$113
0020		IF(Y[NPTS+1]) 10,20,30	S114
0021	20) IF (X(NPTS+1)) 21,22,23	S115
0022	22	CALL AXISIO.O. YPAGE, TITLEX, -NCHARX, LENGX, O.O. X (NPTS+1), X (NPTS+2))	\$116
0023		CALL AXIS(XPAGE, 0.0, TITLEY, NCHARY, LENGY, 90.0, Y(NPTS+1), Y(NPTS+2))	5117
0024		CALL LINE(X,Y,NPTS,1,0,0)	5118
0025		CALL PLOT(PLEND,-11.0, PENP)	\$119
0026		GO TO 99	\$120
0027	21	XPAGE=-X(NPTS+1)/X(NPTS+2)	5121
0028		GO TO 22	5123
0029	23	IF(ORIGN-NE-0-0) GO TO 22	\$127
0030		XMAX=X(NPTS+1)+LENGX*X(NPTS+2)	5128
0031		$X\{NPTS+1\}=0.0$	5129
0032		X(NPTS+2)=XMAX/LENGX	\$130
0033		GO TO 22	\$131
-		\cdot	

	OC34	10 YPAGE=-Y(NPTS+1)/Y(NPTS+2)	\$132
. •	0035	IF(X(NPTS+1)) 11,12,13 ·	\$133
	0036	12 GO TO 22	\$135
	0037	11 XPAGE=-X(NPTS+1)/X(NPTS+2)	\$136
	0038	GO TO 22	\$137
	0039	13 [F(ORIGN.NE.O.O) GO TO 12	\$138
	0040	XMAX=X(NPTS+1)+LENGX*X(NPTS+2)	\$139
	0041	X(NPTS+1)=0.0	\$140
	0042	X(NPTS+2)=XMAX/LENGX	\$141
	0043	GO TO 22	\$142
	0044	30 IF(X(NPTS+1)) 31,32,33	\$158
	0045	32 IF(ORIGN.NE.O) GO TO 22	\$159
	0046	34 YMAX=Y(NPTS+1)+LENGY*Y(NPTS+2)	
9	0047	Y(NPTS+1)=0.0	\$160
	0048	Y(NPTS+2)=YMAX/LENGY	\$161 \$162
٠	0049	GO TO 22	\$163
	0050	31 XPAGE=-X(NPTS+1)/X(NPTS+2)	5164
	0050	GO TO 32	\$166
	0052	33 IF(ORIGN.NE.0.0) GO TO 22	\$170
	0052	XMAX=X(NPTS+1)+LENGX*X(NPTS+2)	\$171
		X(NPTS+1)=0.0	\$172
	0054	X(NPTS+2)=XMAX/LENGX	\$173
	0055	GO TO 34	\$174
	0056		\$175
	0057	99 RETURN	\$176
	0058 .	END	31.10

L	c)	
ā	=		

0.0 -0.718581E-03 0.0 -0.120722E-04 0.0 300.00000000 51 -20.29986572 -10.45541763 13.73689747 10.00000000 0.36341119 -0.179644E-01 -0.898225E-0.00 -0.179644E-01 0.0 -0.301802E-03 0.0 300.00000000 52 -20.70585632 -10.66452599 14.01163197 10.00000000 0.36328059 -0.183237E-01 -0.916189E-0.00 -0.183237E-01 0.0 -0.307838E-03 0.0 300.000000000 0.916189E-0.00 -0.183237E-01 0.0 -0.307838E-03 0.0 300.000000000 0.916189E-0.00 -0.182483E-01 0.0 -0.306570E-03 0.0 300.00000000 0.36330801 -0.182483E-01 -0.912418E-0.00 -0.182483E-01 0.0 -0.306570E-03 0.0 300.00000000 0.36330801 -0.187792E-01 -0.912418E-0.353961E-03 -0.184252E-01 -0.176981E-03 -0.315490E-03 0.128563E-02 300.00000000 0.36330801 -0.442640E-01 -0.912418E-0.173439E-01 -0.269202E-01 -0.867194E-02 -0.743629E-03 0.621992E-01 300.00000000 0.912418E-0.176978E-01 -0.269202E-01 -0.867194E-02 -0.743629E-03 0.621992E-01 300.00000000 0.912418E-0.176978E-01 -0.270972E-01 -0.884892E-02 -0.752549E-03 0.634518E-01 300.00000000 0.912418E-0.176978E-01 -0.270972E-01 -0.884892E-02 -0.752549E-03 0.634518E-01 300.00000000 0.912418E-0.174187E-01 -0.269576E-01 -0.870935E-02 -0.745514E-03 0.35393715 -0.443763E-01 -0.912418E-0.174187E-01 -0.269576E-01 -0.870935E-02 -0.745514E-03 0.624640E-01 300.00000000	J	SIGX EPXP	SIGY EPXE	P EPYE	Y S	V WP	EPX T	GAMME
0.0 -0.718581E-03 0.0 -0.120722E-04 0.0 300.00000000 51 -20.29986572 -10.45541763 13.73689747 10.00000000 0.36341119 -0.179644E-01 -0.898225E-0.0 -0.179644E-01 0.0 -0.301802E-03 0.0 300.000000000 52 -20.70585632 -10.66452599 14.01163197 10.00000000 0.36328059 -0.183237E-01 -0.916189E-0.0 -0.183237E-01 0.0 -0.307838E-03 0.0 300.000000000 NEXT VALUES ARE FOR POINT A 52 -20.62063599 -10.62062836 13.95396423 10.00000000 0.36330801 -0.182483E-01 -0.912418E-0.0 -0.182483E-01 0.0 -0.306570E-03 0.0 300.00000000 53 -21.02662659 -11.02662754 14.35995960 10.00000000 0.36311513 -0.187792E-01 -0.912418E-0.353961E-03 -0.184252E-01 -0.176981E-03 -0.315490E-03 0.128563E-02 300.000000000 101 -40.51417542 -30.51428223 33.84757996 10.00000000 0.35397691 -0.442640E-01 -0.912418E-0.173439E-01 -0.269202E-01 -0.867194E-02 -0.743629E-03 0.621992E-01 300.00000000 102 -40.92016602 -30.92027283 34.25357056 10.00000000 0.353978897 -0.447950E-01 -0.912418E-0.176978E-01 -0.270972E-01 -0.884892E-02 -0.752549E-03 0.634518E-01 300.000000000 NEXT VALUES FOR POINT B 102 -40.5999084 -30.60009766 33.93339539 10.00000000 0.35393715 -0.443763E-01 -0.912418E-0.174187E-01 -0.269576E-01 -0.870935E-02 -0.745514E-03 0.624640E-01 300.00000000 103 -40.19398499 -30.39097595 33.65864563 10.00000000 0.35406429 -0.440170E-01 -0.894453E-01 -0.894453E-02 -0.745514E-03 0.624640E-01 300.000000000000000000000000000000000								
0.0								
0.0	5							
52 -20.62063599 -10.62062836 13.95396423 10.00000000 0.36330801 -0.182483E-01 -0.912418E-0.00	5							
0.0		NEXT VALUES	ARE FOR POINT A					•
-0.353961E-03 -0.184252E-01 -0.176981E-03 -0.315490E-03 0.128563E-02 300.00000000	5							
-0.173439E-01 -0.269202E-01 -0.867194E-02 -0.743629E-03 0.621992E-01 300.00000000 102 -40.92016602 -30.92027283 34.25357056 10.00000000 0.35378897 -0.447950E-01 -0.912418E-0.176978E-01 -0.270972E-01 -0.884892E-02 -0.752549E-03 0.634518E-01 300.00000000 NEXT VALUES FOR POINT B 102 -40.59999084 -30.60009766 33.93339539 10.00000000 0.35393715 -0.443763E-01 -0.912418E-0.174187E-01 -0.269576E-01 -0.870935E-02 -0.745514E-03 0.624640E-01 300.00000000 103 -40.19398499 -30.39097595 33.65864563 10.00000000 0.35406429 -0.440170E-01 -0.894453E-	9 6 5							
-0.173439E-01 -0.269202E-01 -0.867194E-02 -0.743629E-03 0.621992E-01 300.00000000 102 -40.92016602 -30.92027283 34.25357056 10.00000000 0.35378897 -0.447950E-01 -0.912418E-0.176978E-01 -0.270972E-01 -0.884892E-02 -0.752549E-03 0.634518E-01 300.00000000 NEXT VALUES FOR POINT B 102 -40.59999084 -30.60009766 33.93339539 10.00000000 0.35393715 -0.443763E-01 -0.912418E-0.174187E-01 -0.269576E-01 -0.870935E-02 -0.745514E-03 0.624640E-01 300.00000000 103 -40.19398499 -30.39097595 33.65864563 10.00000000 0.35406429 -0.440170E-01 -0.894453E-					•			
-0.176978E-01 -0.270972E-01 -0.884892E-02 -0.752549E-03 0.634518E-01 300.00000000 NEXT VALUES FOR POINT B 102 -40.59999084 -30.60009766 33.93339539 10.00000000 0.35393715 -0.443763E-01 -0.912418E-	10							-0.912418E-02 0
102 -40.59999084 -30.60009766 33.93339539 10.00000000 0.35393715 -0.443763E-01 -0.912418E- -0.174187E-01 -0.269576E-01 -0.870935E-02 -0.745514E-03 0.624640E-01 300.00000000 103 -40.19398499 -30.39097595 33.65864563 10.00000000 0.35406429 -0.440170E-01 -0.894453E-	10							-0.912418E-02 0
-0.174187E-01 -0.269576E-01 -0.870935E-02 -0.745514E-03 0.624640E-01 300.00000000 103 -40.19398499 -30.39097595 33.65864563 10.00000000 0.35406429 -0.440170E-01 -0.894453E-		NEXT VALUES	FOR POINT B					
	10							-0.912418E-02)
	10	•						-0.894453E - 02)

J	SIGX EPXP	SIGY EPXE	P EPYE	Y S	V WP	EPX T	GAMME
203	0.40636444 -0.174187E-01	-9.47920322 0.933193E-02	6.18401051 -0.870935E-	10.00000000 02 -0.135848E-03	0.36701411 0.624640E-	-0.808666E-02 -01 300.00000000	0.902007E-02
204	0.81236434 -0.174187E-01	-9.27009392 0.969123E-02	5.90926552 -0.870935E-	10.00000000 02 -0.129812E-03	0.36714596 0.624640E-	-0.772735E-02 -01 300.00000000	0.919972E-02
	NEXT VALUES FOR	POINT C					
204	0.64233136 -0.174187E-01	-9.35766888 0.954075E-02	6.02433205 -0.870935E-	10.00000000 02 -0.132340E-03	0.36709070 0.624640E-		0.912448E-02
205	1.04833126 -0.170647E-01	-8.95166874 0.971773E-02	5.61833191 -0.853236E-	10.00000000 02 -0.123420E-03	0.36728561 0.637637E-	-0.734688E-02 -01 300.00000000	0.912448E-02
				-			
253	20.53619385 -0.743989E-04		13.86960316 -0.371640E-	10.00000000 04 0.304734E-03	0.37676501 0.126967E	0.181385E-01 00 300.00000000	0.912448E-02
254	20.94218445 0.279562E-03		14.27559853 0.139817E-	10.00000000 03 0.313654E-03		0.186694E-01 00 300.00000000	0.912448E-02
	NEXT VALUES FOR	POINT F					
254	20.61920166 -0.202062E-05		13.95262146 -0.974804E-			0.182470E-01 00 300.00000000	0.912448E-02
255	20.21319580 -0.202062E-05		13.67788124 -0.974804E-	10.00000000 06 0.300521E-03	0.37667054 0.127240E	0.178877E-01 00 300.00000000	0.894483E-02
				-			
303	0.72513318 -0.202062E-05	0.37298089 0.643598E-03	-0.49036467 -0.974804E-	10.00000000 06 0.107875E-04	0.37022889 0.127240E	0.641669E-03 00 300.00000000	0.321765E-03
304	0.31913328 -0.202062E-05		-0.21562606 -0.974804E-	10.00000000 06 0.475146E-05	0.37009585 0.127240E	0.282378E-03 00 300.00000000	0.142119E-03
	NEXT VALUES COM	PLETE THE CYCLE					
305		-0.00049567 0.189035E-05	0.00033045 -0.974804E-	10.00000000 06 0.684031E-08	0.36999130 0.127240E	-0.393484E-07 00 300.00000000	0.910179E-06



Gibbs Relation

Consider an element of mass within which may operate various irreversible processes. The element is supposed to be in a stable or equilibrium state; if it is left undisturbed it remains unchanged. We also suppose that temperature T, specific entropy S, and specific internal energy E can be assigned to it. External forces are applied at a particular instant and work is done on the element in the amount dW. Heat of amount dQ is also added. These external influences set in motion irreversible processes, some of which operate immediately and some of which may operate over an extended time interval. After a long time, during which the element is insulated from further heat exchange, the element is assumed to come to a new equilibrium state which differs from the first by internal energy dE, temperature dT and entropy dS. We suppose that the only net effect of adding dQ and dW is to increase the internal energy:

$$dE = dQ + dW (E1)$$

We further suppose that some method exists for assessing the internal changes in the sample, i.e. for partitioning the change dE into changes in thermal energy, TdS, and coherent energy, say dW_e . For the purposes of Section IV this is accomplished by writing the total work increment as the sum of an elastic and plastic term and assuming that the elastic work is reversible:

$$dW = dW_e + dW_p (E2)$$

$$dE = TdS + dW_{p}$$
 (E3)

Combining Eqs. (E1) - (E3) yields the Gibbs relation

$$TdS = dW_D + dQ (E4)$$

Properties of the material and properties postulated to this point imply that there also exist other thermo-dynamic functions, e.g. the Helmholtz free energy,

$$A = E - TS$$

$$dA = -SdT + dW_{e}$$

$$= -SdT + dW - dW_{p}$$
(E5)


Heat Absorbed in Isothermal Compression

$$E_{\Lambda}$$
 = internal energy at A

$$E_R$$
 = internal energy at B

$$= E_A + dQ + dW$$

from A to B isothermally, <0.



 $\epsilon_x + d \epsilon_x$

$$E = E(T, \epsilon_x, \gamma^e)$$

$$E_{B} = E_{A} + (\partial E/\partial \varepsilon_{X})_{T,\gamma} e^{-d\varepsilon_{X}} + (\partial E/\partial \gamma^{e})_{T,\varepsilon_{Y}} d\gamma^{e}$$

From Eq. (47)

$$dE = TdS - Vpde_{x} + 8V_{\tau}d_{Y}^{e}/3$$

$$dA = -SdT - Vpd\epsilon_{X} + 8V\tau d\gamma^{e}/3$$

Since $d\varepsilon_x = dV/V$, these can also be written

$$dE = TdS - pdV + 8V_T d_Y^e/3$$

$$dA = -SdT - pdV + 8V_T d_Y^e/3$$

The elastic work consists of two terms: one arising from density change and one from elastic shear. Then

$$E_B = E_A + (\partial E/\partial V)_{T,\gamma} e^{dV} + (\partial E/\partial \gamma^e)_{T,V} d\gamma^e$$

$$(\partial E/\partial V)_{T,\gamma}e = (\partial E/\partial V)_{S,\gamma}e + (\partial E/\partial S)_{V,\gamma}e (\partial S/\partial V)_{T,\gamma}e$$

$$= -p + T (\partial S/\partial V)_{T,\gamma} e$$

$$S = -(\partial A/\partial T)_{V,\gamma} e , p = -(\partial A/\partial V)_{T,\gamma} e$$

$$(\partial S/\partial V)_{T,\gamma} e = -(\partial^2 A/\partial V\partial T)_{\gamma} e = (\partial P/\partial T)_{V,\gamma} e$$

Similarly,

$$(\partial E/\partial \gamma^{e})_{T,V} = (\partial E/\partial \gamma^{e})_{S,V} + (\partial E/\partial S)_{V,\gamma^{e}} (\partial S/\partial \gamma^{e})_{T,V}$$

$$= 8V\tau/3 + T(\partial S/\partial \gamma^{e})_{T,V}$$

$$(\partial S/\partial \gamma^{e})_{T,V} = -(\partial^{2}A/\partial T\partial \gamma^{e})_{V,\gamma^{e}} - (8/3)(\partial V\tau/\partial T)_{V,\gamma^{e}}$$

$$= -(8V/3) (\partial \tau/\partial T)_{V,\gamma^{e}}$$

Then

$$dQ = E_{B} - E_{A} - dW = [-p + T(\partial p/\partial T)_{V,\gamma} e^{-\frac{1}{2}}] dV$$

$$+ [8V_{T}/3 - (8VT/3) (\partial \tau/\partial T)_{V,\gamma} e^{-\frac{1}{2}}] d\gamma^{e}$$

$$+ pdV - 8V_{T}d\gamma^{e}/3 - 8V_{T}d\gamma^{p}/3$$

$$dQ = T(\partial p/\partial T)_{V,\gamma} e^{-\frac{1}{2}} dV - (8VT/3) (\partial \tau/\partial T)_{V,\gamma} e^{-\frac{1}{2}} d\gamma^{e} - 8V_{T}d\gamma^{p}/3$$

where $8V_{\tau}d_{\gamma}^{p}/3 = dW_{p}$.

APPENDIX G

Evaluation of
$$(3\sigma_{x}/3T)_{\varepsilon_{x}}^{e}$$
, ε_{y}^{e} and $(3\tau/3T)_{e}^{e}$
From Eq. (27)

$$d\sigma_X = (\lambda + 2\mu) d\varepsilon_X^e + 2\lambda d\varepsilon_y^e$$

where λ and μ are functions of temperature and strain.

Let
$$\lambda_2 = \lambda(T_2, \varepsilon)$$

 $\lambda_1 = \lambda(T_1, \varepsilon)$
 $\mu_2 = \mu(T_2, \varepsilon)$
 $\mu_1 = \mu(T_1, \varepsilon)$

In the neighborhood of a fixed pair of elastic strains, $(\varepsilon_{xol}^e, \varepsilon_{yol}^e)$, σ_x can be represented as a linear function of ε_x^e , ε_y^e :

$$\sigma_{\mathbf{x}}(\mathsf{T}_{1}, \, \varepsilon_{\mathbf{x}}^{e}, \, \varepsilon_{\mathbf{y}}^{e}) = \sigma_{\mathbf{x}}(\mathsf{T}_{1}, \, \varepsilon_{\mathsf{xol}}^{e}, \, \varepsilon_{\mathsf{yol}}^{e})$$

$$+ (\lambda_{1} + 2\mu_{1}) (\varepsilon_{\mathbf{x}}^{e} - \varepsilon_{\mathsf{xol}}^{e}) + 2\lambda_{1}(\varepsilon_{\mathbf{y}}^{e} - \varepsilon_{\mathsf{yol}}^{e})$$

Similarly

$$\sigma_{x}(T_{2}, \varepsilon_{x}^{e}, \varepsilon_{y}^{e}) = \sigma_{x}(T_{2}, \varepsilon_{xo2}^{e}, \varepsilon_{yo2}^{e}) + (\lambda_{2} + 2\mu_{2}) (\varepsilon_{x}^{e} - \varepsilon_{xo2}^{e}) + 2\lambda_{2} (\varepsilon_{y}^{e} - \varepsilon_{yo2}^{e}).$$

Choose ϵ_{xo2}^e and ϵ_{yo2}^e so that $\sigma_x(T_2, \epsilon_{xo2}^e, \epsilon_{yo2}^e) = \sigma_x(T_1, \epsilon_{xo1}^e, \epsilon_{yo1}^e)$. Then

$$\delta\sigma_{x} = (\lambda_{2} + 2\mu_{2}) (\epsilon_{x}^{e} - \epsilon_{xo2}^{e}) + 2\lambda_{2}(\epsilon_{y}^{e} - \epsilon_{yo2}^{e})$$
$$- (\lambda_{1} + 2\mu_{1}) (\epsilon_{x}^{e} - \epsilon_{xo1}^{e}) - 2\lambda_{1}(\epsilon_{y}^{e} - \epsilon_{yo1}^{e})$$

where $\delta \sigma_{x} \equiv \sigma_{x}(T_{2}, \epsilon_{x}^{e}, \epsilon_{y}^{e}) - \sigma_{x}(T_{1}, \epsilon_{x}^{e}, \epsilon_{y}^{e}).$

We have approximately

$$\lambda_2 = \lambda_1 + (\partial \lambda / \partial T) \delta T,$$
 $\mu_2 = \mu_1 + (\partial \mu / \partial T) \delta T$
 $\epsilon_{xo2}^e = \epsilon_{xo1}^e + \alpha_x \delta T$
 $\epsilon_{yo2}^e = \epsilon_{yo1}^e + \alpha_y \delta T$

where α_{χ} and α_{y} are linear thermal expansion coefficients:

$$\alpha_{x} = (\partial \varepsilon_{x}^{e} / \partial T)_{\varepsilon_{y}}^{e}, \sigma_{x}$$

$$\alpha_{y} = (\partial \varepsilon_{y}^{e} / \partial T)_{\varepsilon_{y}}^{e}, \sigma_{y}$$

Then to first order in δT

$$\delta\sigma_{X} = -\alpha_{X}(\lambda_{1} + 2\mu_{1}) \delta T - 2\lambda_{1} \alpha_{y} \delta T$$

$$+ \delta T(\epsilon_{X}^{e} - \epsilon_{X01}^{e}) \delta(\lambda + 2\mu) / \delta T$$

$$+ 2\delta T(\epsilon_{y}^{e} - \epsilon_{y01}^{e}) (\delta \lambda / \delta T)$$

$$(\partial \sigma_{x}/\partial T)_{\varepsilon_{x}}^{e}, \varepsilon_{y}^{e}, \varepsilon_{y}^{e} = \lim_{\substack{e \\ \varepsilon_{x} \to \varepsilon_{x} \text{ol} \\ \varepsilon_{y} \to \varepsilon_{y} \text{ol}}} (\delta \sigma_{x}/\delta T) = -\alpha_{x}(\lambda + 2\mu) - 2\lambda_{1} \alpha_{y}$$


If $\alpha_X = \alpha_y = \alpha/3$, where α is the volume expansion coefficient, then

$$(\partial \sigma_{x}/\partial T)_{\varepsilon} e_{x} e_{y} = -\alpha(\lambda + 2\mu/3) = -K\alpha$$

$$= -(\partial p/\partial T)_{y}$$

Let
$$d\tau = 2\mu d\gamma^e$$

Let $\tau(T_1, \gamma^e) = \tau(T_1, \gamma_{01}^e) + 2\mu(T_1) (\gamma^e - \gamma_{01}^e)$
 $\tau(T_2, \gamma^e) = \tau(T_2, \gamma_{02}^e) + 2\mu (T_2) (\gamma^e - \gamma_{02}^e)$
Let $\tau(T_2, \gamma_{02}^e) = \tau(T_1, \gamma_{01}^e)$



Then

$$\tau(T_{2},\gamma^{e}) - \tau(T_{1},\gamma^{e}) = \delta\tau = 2\mu(T_{2}) (\gamma^{e} - \gamma_{02}^{e}) - 2\mu(T_{1}) (\gamma^{e} - \gamma_{01}^{e})$$

Let
$$\mu(T_2) = \mu(T_1) + (dT/d\mu) (T_2 - T_1)$$
.


Then

$$\delta \tau = -2\mu(T_1) (\gamma_{02}^{e} - \gamma_{01}^{e}) + 2(T_2 - T_1) (dT/d\mu) (\gamma^{e} - \gamma_{02}^{e}).$$

Let
$$\delta T \equiv T_2 - T_1 \rightarrow 0$$
, $\gamma_{02}^e \rightarrow \gamma_{01}^e$, $\gamma^e \rightarrow \gamma_{02}^e$

$$\delta \tau / \delta T \rightarrow (\partial \tau / \partial T)_{\tau} e = -2\mu(T_1)(\partial \gamma^e / \partial T)_{\tau}$$

$$\gamma^e$$
 = const. implies $d\gamma^e = d(\epsilon_x^e - d\epsilon_y^e)/2 = 0$.



Multiplication Time for Dislocations

Suppose that each dislocation runs freely between imperfections without multiplying, reaches an imperfection, hesitates, multiplies and goes on to the next. If the distance between imperfections is ℓ and shear velocity in the crystal is v_s , the multiplication time is the order of

$$t_0 = \ell/v_s + t_h$$

where t_h = hesitation time at the imperfection.

Let t_h be determined by a rate process. A dislocation is trapped at a site and must surmount an energy barrier, U, to escape. It makes n escape tries per second and the probability that any one of them will succeed is assumed to be $\exp(-U/kT)$. Let P(M + 1) = probability that escape occurs on the $(M + 1)^{th}$ trial. Then

$$P(M + 1) = [1 - exp(-U/kT)]^{M} exp(-U/kT)$$

$$= (probability that first M tries fail) x$$

$$(probability that (M + 1)^{th} succeeds).$$

Also
$$P(M + J) = P(M + 1) [1 - exp (- U/kT)]^{J-1}$$
.

The probability that escape occurs on the $(M + 1)^{th}$, $(M + 2)^{th}$, ..., or $(M + J)^{th}$ try is

$$\sum_{r=1}^{J} P(M+r) = P(M+1) (1-a^{J})/(1-a)$$

where $a \equiv 1 - \exp(-U/kT)$.

Since there are n tries per second, M = nt. Let J = ndt, then

Neglecting the higher order quantities, we have the result that

$$P(t)dt = -[1 - exp(-U/kT)]^{nt} ln[1 - exp(-U/kT)] ndt$$

where P(t)dt = probability that escape occurs during the interval (t, t + dt). It is readily verified that

$$\int_0^\infty P(t) dt = 1$$

Then the mean time for escape is

$$t_h = \int_0^\infty tP(t)dt$$

$$= -(1/n) / ln[1 - exp(-U/kT)]$$

$$\simeq exp(U/kT)/n \text{ if } exp(-U/kT) << 1.$$

The multiplication time is then

$$t_0 = \ell/v_S - (1/n) / ln[1 - exp (-U/kT)]$$
 (H1)

for exp (-U/kT) < 1. The effect of applied stress is to diminish U, e.g.

$$U = U_0 (1 - \sigma/\sigma_0)$$

where σ_0 is a critical or threshold stress. For $\sigma \geq \sigma_0$, Eq. (H1) is replaced by

$$t_0 = \ell/v_s$$
.

APPENDIX I

Functional dependence of p and μ

$$\partial^2 p / \partial T \partial \gamma^e = -(8/3) \partial (V \partial \tau / \partial T) / \partial V$$
 (86a)

$$a^2 p / \partial N \partial T = -a^2 r / \partial V \partial T \tag{86b}$$

$$\partial^2 r / \partial T \partial \gamma^e = (8/3) \partial (V \partial \tau / \partial T) / \partial N$$
 (86c)

Let
$$\tau = 2\mu\gamma^e$$
 (I1)

$$\partial \mu / \partial \gamma^{e} = 0 \tag{12}$$

Let
$$r = b^2 \mu V/2$$
 (I3)

Eq. (86a), with (II) becomes

$$a^2p/\partial T\partial \gamma^e = -(16\gamma^e/3) \partial (V\partial \mu/\partial T)/\partial V$$

$$= -(16\gamma^{e}/3) \quad \partial^{2}(\mu V)/\partial T\partial V \tag{14}$$

If
$$\partial p/\partial y^{e} = 0$$
 (I5)

Then Eq. (I4) becomes

$$\theta^2(\mu V)/\theta T\theta V = 0 \tag{16}$$

or
$$\partial(\mu V)/\partial T = f_1(T, \gamma^e, N)$$
 (I7)

In view of Eq. (I2), (I7) becomes

$$\partial(\mu V)/\partial T = f_1(T,N). \tag{18}$$

From Eqs. (86b) and (I3),

$$\partial^2 p/\partial N \partial T = -(b^2/2) \partial^2 \mu V/\partial V \partial T$$
 (19)

Equations (I9) and (I6) combine to yield

$$\partial^2 p/\partial N\partial T = 0. (I10)$$

Equation (I10) implies that

$$\partial p/\partial T = f_2(T, \gamma^e, V)$$
 (III)

Since p is already assumed to be independent of γ^e , Eq. (I11) becomes

$$\partial p/\partial T = f_2(T,V). \tag{112}$$

Equations (86c), (II) and (I3) combine to give

$$(b^2/2) \ \partial^2(\mu V)/\partial T \partial \gamma^e = (16\gamma^e/3) \ \partial^2(\mu V)/\partial T \partial N$$
 (113)

By Eq. (I2) μ is independent of γ^e , so the left hand side of Eq. (I13) is zero. Then

$$\partial^2(\mu V)/\partial T \partial N = 0 \tag{114}$$

so,

$$\partial(\mu V)/\partial T = f_3(T,V,\gamma^e)$$
 (I15)

Comparing Eqs. (I8) and (I15) shows that

$$\partial(\mu V)/\partial T = f_1(T) \tag{116}$$

Integration of Eqs. (I12) and (I16) yields

$$p = f(T,V) + g(V,N)$$
 (I17)

$$\mu V = F(T) + G(V,N) \tag{118}$$

where the assumptions that p and μ are independent of γ^e have been carried forward into Eqs. (I17) and (I18).

Temperature Dependence of Shear Modulus of Al

Equation (75) is obtained from Eqs. (70) under the assumptions that pressure and specific heat, $C_{\gamma\gamma}$, are both independent of γ^e , and that τ is proportional to γ^e :

$$\mu = \mu_0 + b(T/V - T_0/V_0) + \phi(V)$$
 (J1)

Such a linear dependence is quite reasonable for small deviations from T_0 , but must clearly be inadequate as T approaches the melting temperature, T_m . If one assumes that the reduction of μ with temperature is an activated process and that μ vanishes at $T = T_m$, he obtains an equation of the form

$$\mu = c \exp[-A/(T_m - T)]$$
 (J2)

This function varies slowly with T until it approaches T_m , then decreases precipitously in value. To give it the linear form of Eq. (J1), for small T - T_0 , let μ be given by the expression

$$\mu = c \exp[-A/(T_m - T)] [1 - b(T - T_0)]$$
 (J3)

Measurements made by P. M. Sutton (1953) have been used to evaluate the constants in Eq. (J3) with $T_{\rm o}$ = 273.2°K. The result is

$$\mu$$
(megabars) = .2812 exp [-7.8059/(933.2 - T)]
 [1 - 4.79 x 10^{-4} (T - 273.2)] (J4)

Values calculated from Eq. (J4) are compared with Sutton's measured values in the following table:

T = 273.2 373.2 473.2 573.2 673.2 773.2 873.2 903.2 933.2
$$\mu_{\text{calc}} = .2812$$
 .2672 .2530 .2384 .2232 .2061 .1780 .153 0 $\mu_{\text{meas}} = .2812$.2670 .2530 .2385 .2232 .2063

These values are plotted in Fig. Jl.

It would improve the form of (J3) to write it as

$$\mu = c \exp[-A/(T_m - T)][1 - B'(T/V - T_o/V_o)]$$
 (J5)

In that case

$$b' \simeq 1.8 \times 10^{-4} \text{ cc/g}^{\circ}\text{K}$$
.

However, one can argue that the parameter A should also be volume dependent, so the refinement of (J5) hardly seems worthwhile at present.

A different form of the temperature dependence of elastic constants has been given by Varshni (1970). It describes the slow variation satisfactorily but does not vanish at $T = T_m$. For the present purpose the behavior near $T = T_m$ is important because it relates to the annealing properties of dislocations.




Figure J1 C_{44} of A1 according to the formula $C_{44} = .2812 \exp[-7.8059/(933.2-T]]$ $[1 - 4.79 \times 10^{-4} (T-273.2)]$

This corresponds closely to data given by P. M. Sutton (1953).

REFERENCES

- Arndt, R. A., and F. E. Fujita, Rev. Sci. Instr. 34, 868 (1963)
- Asay, J. R., G. R. Fowles, G. E. Duvall, M. H. Miles and R. F. Tinder, "Effects of Point Defects on Elastic Precursor Decay in LiF," J. Appl. Phys. 43, #5, 2132 (1972)
- . Aström, H. U., Arkiv Fysik 10, 197 (1956)
- Åström, H. U., Arkiv Fysik 26, 83 (1964)
- Bailey, J. E. and P. B. Hirsch, Phil. Mag. 5, 485 (1960)
- Basinski, Z. S., Phil. Mag. 4, 393 (1959)
- Bever, M. B. and L. B. Ticknor, J. Appl. Phys. 22, 1297 (1951)
- Boas, W., <u>Dislocations and Mechanical Properties of Crystals</u>, John Wiley & Sons, New York (1957)
- Borelius, G., S. Berglund and S. Sjöberg, Arkiv Fysik 6, 143 (1953)
- Bridgman, P. W., "The Thermodynamics of Plastic Deformation and Generalized Entropy," Rev. Mod. Phys. 22, #1, 56 (1950)
- Calvet, E. and H. Prat, <u>Recent Progress in Microcalorimetry</u>, McMillan, New York (1963)
- Clarebrough, L. M., M. E. Hargreaves, D. Mitchell and G. W. West, Proc. Roy. Soc. (London) A215, 507 (1952)
- Clarebrough, L. M., M. E. Hargreaves, A. K. Head and M. H. Loretto, Phil. Mag. Ser. 8, 6, 819 (1961)
- Coleman, B. D. and M. E. Gurtin, J. Chem. Phys. <u>47</u>, 597 (1967)
- Coleman, B. D. and W. Noll, Arch. Rat. Mech. Anal. <u>13</u>, 167 (1963)
- Cottrell, A. H., <u>Dislocations and Plastic Flow in Crystals</u>, Oxford Clarendon Press, U.K. (1953)
- DeGroot, S. R., <u>Thermodynamics of Irreversible Processes</u>, North Holland Publishing Co., Amsterdam (1951)
- DeGroot, S. R., and P. Mazur, <u>Non-Equilibrium Thermodynamics</u>, North Holland Publishing Co., Amsterdam (1962), p. 333.
- Dillon, O. W. Jr., J. Mech. Phys. Solids 10, 235 (1962)
- Dillon, O. W. Jr., J. Appl. Phys. 33, 3100 (1962)

- Dillon, O. W. Jr., Int. J. Solids Structures 2, 181 (1966)
- Dillon, O. W. Jr., <u>Mechanical Behavior of Materials under Dynamics Loads</u>, U. S. Lindholm, Ed., Springer-Verlag, New York (1968)
- Dillon, O. W. Jr., and J. Kratchovil, "Thermodynamics of Crystalline Elastic-Visco-Plastic Materials," J. Appl. Phys. 41, #4, 1470 (1970)
- Eckart, C., "The Thermodynamics of Irreversible Processes. IV. The Theory of Elasticity and Anelasticity," Phys. Rev. 73, #4, 373 (1948)
- Epifanov, G. I. and P. A. Rebinder, Dokl. Akad. Nauk. SSSR, 66, 653 (1949)

Erdmann, J. C. and J. A. Jahoda, Rev. Sci. Instr. 34, 172 (1964)

Eugene, F., C. R. Acad. Sci. Paris, 236, 2071 (1953)

Eugene, F., Microtecnic (Lausanne) 8, 127 (1954)

Farren, W. S. and G. I. Taylor, Proc. Roy. Soc. (London) A107, 422 (1925)

Frank, F. C., "Crystal Dislocations--Elementrary Concepts and Definitions," Phil. Mag. 42, 809 (1951)

Friedel, J., Phil. Mag. 46, 1169 (1955)

Gilman, J. J. Micromechanics of Flow in Solids, McGraw-Hill Inc., New York (1969)

Gordon, P., Rev. Sci. Instr. 25, 1173 (1954)

Gordon, P., Trans. AIME, 203, 1043 (1955)

Henderson, J. W. and J. S. Koehler, Phys. Rev. <u>104</u>, 626 (1956)

Hirsch, P. B., Report of <u>Symposium on Internal Stresses and Fatigue in Metals</u> Elsevier, New York (1958)

Hort, H., Z. Ver Dtsch. Ing., <u>50</u>, 1831 (1906)

Hort, H., Mitt. Forsch. Arb. Ing. 41, 1 (1907)

Howlett, B. W., J. S. L. Leach, L. B. Ticknor and M. B. Bever, Rev. Sci. Instr. 33, 619 (1962)

Kluitenberg, G. A., "On the Thermodynamics of Viscosity and Plasticity," Physica, 29, 633 (1963)

Kunin, N. F. and G. V. Senolov, Tr. Sibirsk. Fiz. Tekhn. Inst. Pri. Tomsk. Gos. Univ. 4, 132 (1936)

Maier, C. G. and C. T. Anderson, J. Chem. Phys. 2, 513 (1934)

Meixner, J., Z. Physik 193, 366 (1966)

- Nabarro, F. R. N., <u>Theory of Crystal Dislocations</u>, Oxford University Press, London (1967) p. 694
- Orowan, E., Z. Phys. 89, 634 (1934)
- Polanyi, M., Z. Phys. <u>89</u>, 660 (1934)
- Prigogine, I., <u>Introduction to Thermodynamics of Irreversible Processes</u>, Interscience, New York (1967) p. 7
- Proceedings of the Cambridge Philosophical Society, "The Origins of Clerk Maxwell's Electric Ideas, As Described in Familiar Letters to W. Thomson," Cambridge University Press, 32, Part 5, 695 (1936)
- Quinney, H. and G. I. Taylor, Proc. Roy. Soc. (London) A163, 157 (1937)
- Reiner, M., Handbuch der Physik, Vol. VI., Springer-Verlag, Berlin (1958)
- Satô, H., Sci. Report Tôhoku Univ. 20, 140 (1931)
- Seeger, A., J. Diehl, S. Mader and H. Rebstock, Phil. Mag. 2, 232 (1957)
- Sherwin, K. A., J. Sci. Instr. 41, 7 (1964)
- Smith, C. J., Proc. Roy. Soc. (London) A125, 619 (1929)
- Stansbury, E. E., D. L. McElroy, M. L. Pickelsimer, G. E. Elder and R. E. Pawel, Rev. Sci. Instr. 30, 121 (1959)
- Sutton, P. M., "The Variation of the Elastic Constants of Crystalline Aluminum with Temperatures Between 63°K and 773°K," Phys. Rev. 91, 816 (1953)
- Taylor, G. I., Proc. Roy. Soc. (London) A145, 362 (1934)
- Taylor, G. I. and H. Quinney, Proc. Roy. Soc. (London) A143, 307 (1934)
- Timoshenko, S. P., <u>History of Strength of Materials</u>, McGraw-Hill Inc., New York (1953)
- Tolman, R. C. and P. C. Fine, Rev. Mod. Phys. 20, 51 (1948)
- Van den Beukel, A., Acta Met. 11, 97 (1963)
- Varshni, Y. P., "Temperature Dependence of the Elastic Constants," Phys. Rev. <u>B2</u>, 3952 (1970)
- Webster, G. A., "A Widely Applicable Dislocation Model of Creep," Phil. Mag. 14, 775 (1966)
- Welber, B., J. Appl. Phys. <u>23</u>, 876 (1952)
- Williams, R. O., Rev. Sci. Instr. 31, 1336 (1960)
- Williams, R. O., Acta. Met. 9, 949 (1961)

Williams, R. O., Trans. AIME, <u>224</u>, 719 (1962)

Williams, R. O., Trans. AIME, <u>227</u>, 1290 (1963)

Williams, R. O., Rev. Sci. Instr. 34, 639 (1963)

Williams, R. O., in <u>Experimental Methods of Materials Research</u>, Herbert Herman, Ed. Wiley & Sons, New York (1967)

Wolfenden, A. and A. S. Appleton, unpublished work, University of Liverpool (1963)

)	
							,		
								,	
					:		,		
			•		4 4				
		•					*	•	
								1 1	â ,
							•		
							1		
							i.		
				•					
		-	•						
					,				
				·					
	•.				,				
•									
									\$
							•		
	•								e ·
	,								
		•			•				
						•			
	•								
				. •	1	•			

No. of Copies		No. of Copies	
	Commander Defense Documentation Center ATTN: TIPCR Cameron Station Alexandria, Virginia 22314	1	Commander U.S. Army Materiel Command ATTN: AMCRD, Dr.J.V.R.Kaufman 5001 Eisenhower Avenue Alexandria, Virginia 22304
	Director Defense Advanced Research Projects Agency 1400 Wilson Boulevard Arlington, Virginia 22209		Commander U.S. Army Materiel Command ATTN: AMCRD-TE 5001 Eisenhower Avenue Alexandria, Virginia 22304
	Director Weapons Systems Evaluation Group Washington, DC 20305		Commander U.S. Army Materiel Command ATTN: AMCRD-TP 5001 Eisenhower Avenue Alexandria, Virginia 22304
_	Director Institute for Defense Analysis 400 Army-Navy Drive Arlington, Virginia 22202		Commander U.S. Army Aviation Systems Command ATTN: AMSAV-E
,	Director Defense Nuclear Agency ATTN: STSP Washington, DC 20305	1	12th and Spruce Streets St. Louis, Missouri 63166 Director U.S. Army Air Mobility Research
	Commander U.S. Army Materiel Command ATTN: AMCDL 5001 Eisenhower Avenue Alexandria, Virginia 22304	2	and Development Laboratory Ames Research Center Moffett Field, California 94035 Commander U.S. Army Electronics Command
	Commander U.S. Army Materiel Command ATTN: AMCDMA, MG J.R.Guthrie 5001 Eisenhower Avenue Alexandria, Virginia 22304		ATTN: AMSEL-RD AMSEL-CE Fort Monmouth, New Jersey 07703
	Commander U.S. Army Materiel Command ATTN: AMCRD, MG S. C. Meyer 5001 Eisenhower Avenue Alexandria, Virginia 22304		Commander U.S. Army Missile Command ATTN: AMSMI-R AMSMI-RSD AMCPM-PE AMCPM-LC Redstone Arsenal, Alabama 35809

•			·
No. of		No. of	
Copies	Organization	Copies	Organization
1	Commander U.S. Army Tank Automotive Command ATTN: AMSTA-RHFL Warren, Michigan 48090		Commander U.S. Army Harry Diamond Laboratories ATTN: AMXDO-TD/002 Washington, DC 20438
3	Commander U.S. Army Mobility Equipment Research & Development Cente ATTN: Tech Docu Cen, Bldg. 31 AMSME-RZT SMEFB-MW Fort Belvoir, Virginia 22060	- er .5	Commander U.S. Army Materials and Mechanics Research Center ATTN: AMXMR-ATL Watertown, Massachusetts 02172 Commander
1	Commander U.S. Army Munitions Command ATTN: AMSMU-RE Dover, New Jersey 07801	. 3	U.S. Army Natick Laboratories ATTN: AMXRE, Dr. D. Sieling Natick, Massachusetts 01762 HQDA (DARD-MS, Dr. W. Taylor; DARD-ARP; DARD-MD, Dr.P. Friel)
. 1	Commander U.S. Army Frankford Arsenal ATTN: SMUFA-C2500 Philadelphia, Pennsylvania 19137	3	Washington, DC 20310 Commander U.S. Naval Air Systems Command ATTN: AIR-604 Washington, DC 20360
2	Commander U.S. Army Picatinny Arsenal ATTN: SMUPA-V SMUPA-VK Dover, New Jersey 07801	3	Commander U.S. Naval Ordnance Systems Command ATTN: ORD-9132 Washington, DC 20360
-	Commander U.S. Army Weapons Command ATTN: AMSWE-RE AMSWE-RDF Rock Island, Illinois 61202		Commander U.S. Naval Weapons Center China Lake, California 93555
1	Director U.S. Army Advanced Materiel Concepts Agency 2461 Eisenhower Avenue	1	Director U.S. Naval Research Laboratory ATTN: Code 6240, Mr. Atkins Washington, DC 20390
	Alexandria, Virginia 22314	1	AFATL (DLR) Eglin AFB Florida 32542

No. of Copies	· ·	No. of Copies	
1	AFATL (DLRV) Eglin AFB, Florida 32542	1	AVCO Corpoation Research & Advance Department 201 Lowell Street
1	AFATL (DLRD) Eglin AFB, Florida 32542		Wilmington, Massachusetts 01887
1	Wright-Patterson AFB Ohio 45433	1	Defense Metals Info. Center Battelle Memorial Institute Columbus Laboratories 505 King Avenue Columbus, Ohio 43201
1	Director U.S. Bureau of Mines ATTN: Mr. R. Watson 4800 Forbes Street Pittsburgh, Pennsylvania 15123	1	General Motors Corporation Manufacturing Development ATTN: Mr. W. Isbell Warren, Michigan 48090
1	Director Environmental Science Services Administration ATTN: Code R, Dr. J. Rinehart		Grumman Aircraft Corporation Bethpage, New York 11714 Hughes Aircraft Company
. 1	U.S. Department of Commerce Boulder, Colorado 80302	_	Research & Development Laboratory Centinela & Teale Street Culver City, California 90232
*	Lawrence Livermore Laboratorie ATTN: Dr. M. Wilkins P. O. Box 808 Livermore, California 94550	s 1	Kaman Nuclear Division Garden of the Gods Road Colorado Springs, Colorado 80907
1	Director Los Alamos Scientific Laborato P. O. Box 1663 Los Alamos, New Mexico 87544		Philco-Ford Corporation Aeronautical Division ATTN: Dr. M. Boyer Ford Road Newport Beach, California
1	Director National Aeronautics and Space Administration Langley Research Center Langley Station Hampton, Virginia 23365		Physics International Corp. ATTN: Dr. C. Godfrey 2700 Merced Street San Leandro, California 94577
1	Aerospace Corporation P. O. Box 95085 Los Angeles, California 90045		

No. of Copies		No. of Copies	Organization
1	Sandia Corporation P.O. Box 5800 Albuquerque, New Mexico 8711	1 5	Pénnsylvania State University Department of Engineering Mechanics ATTN: Prof. N. Davids
3	Systems, Science & Software ATTN: Dr. J. Walsh Dr. J. Dienes		University Park, Pennsylvania 16802
	Dr. T. Riney P.O. Box 1620 La Jolla, California 92037	.1	Southwest Research Institute ATTN: Dr. W. Baker 8500 Culebra Road San Antonio, Texas 78228
1	Brown University Division of Engineering ATTN: Prof. P. Symonds Providence, Rhode Island 029	1	Stanford Research Institute Poulter Laboratories ATTN: Dr. M Cowperthwaite 333 Rayenswood Avenue
1	Drexel Institute of Technolog Wave Propagation Research Cen ATTN: Prof. P. Chou Philadelphia, Pennsylvania 1	ter 1	Menlo Park, California 94025 Stanford University Dept. of Mechanical Engineering
1	University of Dayton Research Institute ATTN: Mr. H. F. Swift Dayton, Ohio 45409	1	ATTN: Prof. E. H. Lee Stanford, California 94305 University of Illinois Dept. of Aeronautical Engineering
2	The Johns Hopkins University Mechanics Department ATTN: Prof. J. Bell Prof. R. Green 34th & Charles Street Baltimore, Maryland 21218	1	ATTN: Prof. R. Strehlow Urbana, Illinois 61803
1	Lincoln Laboratory 244 Wood Street Lexington, Massachusetts 021	1	University of Texas Department of Engineering Mechanics ATTN: Prof. H. Calvit
	Massachusetts Institute of Technology Aerolastic & Structures Laboratory 77 Massachusetts Avenue Cambridge, Massachusetts 921	1	Austin, Texas 78712 Washington State University Department of Physics ATTN: Prof. G. Duvall Pullman, Washington 99163

Aberdeen Proving Ground

Ch, Tech Lib
Marine Corps Ln Ofc
CDC Ln Ofc
CMDR, USAEA
ATTN: SMUEA-AG
DIR, USAMSAA

ATTN: Dr. J. Sperrazza

UNCLASSIFIED Security Classification DOCUMENT CONTROL DATA - R & D (Security Classification of title, body of abstract and indexing annotation must be entered when the overall report is classified) . ORIGINATING ACTIVITY (Corporate author) 28. REPORT SECURITY CLASSIFICATION Washington State University UNCLASSIFIED Department of Physics Pullman, Wa. 99163 REPORT TITLE THEORY OF EQUATIONS OF STATE: ELASTIC-PLASTIC EFFECTS II 4. DESCRIPTIVE NOTES (Type of report and inclusive dates) Scientific Final 5. AUTHOR(5) (First name, middle initial, last name) George E. Duvall and D. P. Dandekar 6. REPORT DATE 78, TOTAL NO. OF PAGES 7b. NO. OF REFS MAY 1973 123 73 88. CONTRACT OR GRANT NO. 98. ORIGINATOR'S REPORT NUMBER(5) DAAD05-71-C-0136 b. PROJECT NO. BRL CONTRACT REPORT NO. 106 9b. OTHER REPORT NO(S) (Any other numbers that may be assigned this report) WSU-SDL 72-01 Approved for public release; distribution unlimited.

Ballistic Research Laboratory
Aberdeen Proving Ground, Md. 21005

After a brief review of the history of material failure studies and of measurements of stored energy in plastically deformed bodies, energy and stress and strain relations are developed for both elastic and plastic deformation in uniaxial strain. The physical effects of plastic deformation are discussed and foundations are laid for thermodynamic calculations of plastically deformed materials. Calculations of both thermodynamic and mechanical parameters are described for uniaxial strain with and without energy storage in internal strains. Conditions of uniaxial strain are found to yield new thermodynamic relations which are useful for synthesizing constitutive relations.

DD FORM 1473

Unclassified
Security Classification